

# ANNUAL SURVEYS.

15925

No. 58. Survey held at London Date April 9 1850  
on the 13<sup>th</sup> James Gibb Master R. Jackson  
Tonnage 696 Built at Quebec When built 1847  
By whom built 174 Owners N. Gibson  
Port belonging to London Destined Voyage Port Phillip  
If Surveyed Afloat or in Dry Dock In Carter's Dry Dock

No. 15 April

Last Survey, No. 14850 Port of London Classed 5 A 1

1 mo 49

present Condition of the

Planks	Treenails	Windlass and Capstan
Stairways	Breasthooks and Stemson	Pumps
Roofings	Transoms, Pointers, and Crutches	Boats
Upper Deck Beams & Fastenings	Timbers of the Frame	Masts, Yards, &c.
Lower Deck Beams & Fastenings	Keelsons	Sails
Plank sheers	Clamps and Shelves	Anchors No. of <u>3 1/2</u>
Strakes	Ceiling	Cables
Sides	Rudder	Hawsers and Warps
Planks	Copper <u>F&amp;G M</u> When put on <u>49</u>	Standing & Running Rigging
Plank (Bottom) and Counter		

General Observations and Opinion,

Now done Dock - to examine Bottom, about 4 sheets expended in painting Yellow Metal, an Iron Hook introduced outside Bows Aloft, Deck Caulked; Rigging stripped and overhaul'd.

Committee Minute

16th April 1850

1850

She appears in very good condition eligible to remain as classed A 1

Character assigned

5 A 1

J. A. Martin

J. A. Martin

Certificate (if required)

No. 56. Survey held at London Date April 11 1850  
on the 13<sup>th</sup> Surge Master Maurice  
Tonnage 411 Built at India When built 1843  
By whom built 530 Owners Phillipps & Co.  
Port belonging to London Destined Voyage  
If Surveyed Afloat or in Dry Dock In Mess<sup>r</sup> Wigram's Dry Dock

No. 15 April

Last Survey, No. 14304 Port of London Classed 10 A 1

40

present Condition of the

Planks	Treenails	Windlass and Capstan
Stairways	Breasthooks and Stemson	Pumps
Roofings	Transoms, Pointers, and Crutches	Boats
Upper Deck Beams & Fastenings	Timbers of the Frame	Masts, Yards, &c.
Lower Deck Beams & Fastenings	Keelsons	Sails
Plank sheers	Clamps and Shelves	Anchors No. of <u>3 1/2</u>
Strakes	Ceiling	Cables
Sides	Rudder	Hawsers and Warps
Planks	Copper <u>F&amp;G Metal</u> When put on <u>40</u>	Standing & Running Rigging
Plank (Bottom) and Counter		

General Observations and Opinion,

Now done: Yellow Metal Sheathing repaired, around Stations and Hatchways Caulked. She appears to be in very good condition

Committee Minute

16th April 1850

1850

eligible to remain as classed A 1

Character assigned

10 A 1

J. A. Martin

J. A. Martin

Certificate (if required)