

LON 628-0459

ANNUAL SURVEYS.

16150

Reg 15/7/50

No. 68 Survey held at London Date 13th July 1850
 on the Sch "Ada" Master Custance
 Tonnage 127 Built at London When built 1844
 By whom built Owners Custance
 Port belonging to London Destined Voyage Mogadore
 If Surveyed Afloat or in Dry Dock in Sweetings Dock

Last Survey, No. 1211 Port of London Classed 11 A 1

The present Condition of the

| | | |
|-------------------------------|----------------------------------|----------------------------|
| Decks | Treenails | Windlass and Capstan |
| Waterways | Breasthooks and Stemson | Pumps |
| Comings | Transoms, Pointers, and Crutches | Boats |
| Upper Deck Beams & Fastenings | Timbers of the Frame | Masts, Yards, &c. |
| Lower Deck Beams & Fastenings | Keelsons | Sails |
| Planksheers | Clamps and Shelves | Anchors No. of |
| Sheerstrakes | Ceiling | Cables |
| Topsides | Rudder | Hawsers and Warps |
| Wales | Copper | Standing & Running Rigging |
| Plank (Bottom) and Counter | | |

General Observations and Opinion, at present bottom stripped Caulked
and Sheathed with yellow metal on paper
appears in efficient Condition and may
16th July 1850 remain as Clapped
 Committee Minute 11 A 1
 Character assigned 11 A 1

Certificate (if required)

No. 373 Survey held at London Date 22nd Dec^r 1848
 on the Ship "Isaac" Master Sulham
 Tonnage 476 Built at Seith When built 1834
 By whom built Owners Marshall &
 Port belonging to London Destined Voyage Australia
 If Surveyed Afloat or in Dry Dock in Swender & London Docks

Last Survey, No. 14578 Port of London

Classed SS 1848 expunged

The present Condition of the

| | | |
|-------------------------------|----------------------------------|----------------------------|
| Decks | Treenails | Windlass and Capstan |
| Waterways | Breasthooks and Stemson | Pumps |
| Comings | Transoms, Pointers, and Crutches | Boats |
| Upper Deck Beams & Fastenings | Timbers of the Frame | Masts, Yards, &c. |
| Lower Deck Beams & Fastenings | Keelsons | Sails |
| Planksheers | Clamps and Shelves | Anchors No. of |
| Sheerstrakes | Ceiling | Cables |
| Topsides | Rudder | Hawsers and Warps |
| Wales | Copper | Standing & Running Rigging |
| Plank (Bottom) and Counter | | |

General Observations and Opinion, at present entirely new skin of Head
fitted with new rails & cheeks outside plating
of the loggattant fore castle renewed timbers appear
generally sound & good she is in efficient Condition
 Committee Minute 16th July 1848
 Character assigned 11 A 1
and in our opinion for the safe
navigation beyond of dry dockable
to & from all parts of Certificate (if required)
report & survey on Clapped