

# ANNUAL SURVEYS.

*Now the "Shepherd" name*  
 No. 358 Survey held at London Date July 20<sup>th</sup> Aug<sup>r</sup> 1850  
 on the B<sup>t</sup> Johan Friedrich Master A Reid  
 Tonnage 323 Built at Rostock When built 1840  
 By whom built \_\_\_\_\_ Owners Martin & Co  
 Port belonging to Dundee Destined Voyage \_\_\_\_\_  
 If Surveyed Afloat or in Dry Dock In New Crane Dry Dock

Last Survey, No. 1494 Port of Dundee Classed 7A1  
49

The present Condition of the

Decks	Treenails	Windlass and Capstan
Waterways	Breasthooks and Stemson	Pumps
Comings	Transoms, Pointers, and Crutches	Boats
Upper Deck Beams & Fastenings	Timbers of the Frame	Masts, Yards, &c.
Lower Deck Beams & Fastenings	Keelsons	Sails
Planksheers	Clamps and Shelves	Anchors No. of
Sheerstrakes	Ceiling	Cables
Topsides	Rudder	Hawsers and Warps
Wales	Copper	Standing & Running Rigging
Plank (Bottom) and Counter	When put on	

General Observations and Opinion, Left Notice Card with the Captain July 20<sup>th</sup>  
Recommending that the Worned Planking of Wales, Bottom  
be dubbed over, and the bad portions removed, before Repairing  
her  
She has left the Dry Dock this morning

Committee Minute 2<sup>nd</sup> Aug<sup>r</sup> 1850 (Aug<sup>r</sup> 1<sup>st</sup>) for Scotland to Repair the  
 Character assigned See Dundee 1504 Defence J A Martin Letter to book  
Q Dundee  
3/8/50  
 Certificate (if required)

No. 403 Survey held at London Date July 29<sup>th</sup> Aug<sup>r</sup> 1850  
 on the Bk Wm Bull Master Duff  
 Tonnage 436 Built at Sunderland When built 1846  
 By whom built \_\_\_\_\_ Owners Templesey  
 Port belonging to London Destined Voyage Montreal  
 If Surveyed Afloat or in Dry Dock Afloat

Last Survey, No. 14095 Port of London 1848 Classed 7A1

The present Condition of the

Decks <u>Good</u>	Treenails <u>good</u>	Windlass and Capstan <u>good</u>
Waterways <u>"</u>	Breasthooks and Stemson <u>"</u>	Pumps <u>"</u>
Comings <u>"</u>	Transoms, Pointers, and Crutches <u>"</u>	Boats <u>"</u>
Upper Deck Beams & Fastenings <u>"</u>	Timbers of the Frame <u>good wherever</u>	Masts, Yards, &c. <u>"</u>
Lower Deck Beams & Fastenings <u>"</u>	Keelsons <u>good</u>	Sails <u>well found</u>
Planksheers	Clamps and Shelves <u>"</u>	Anchors No. of <u>3 Bowers 1 Stm 2 Hedges</u>
Sheerstrakes	Ceiling <u>"</u>	Cables <u>well found</u>
Topsides <u>Good</u>	Rudder <u>"</u>	Hawsers and Warps <u>"</u>
Wales	Copper	Standing & Running Rigging <u>good</u>
Plank (Bottom) and Counter	When put on <u>1847</u>	

General Observations and Opinion, Caulked from the copper overall and is in a very efficient state  
to retain her present class

Committee Minute 2<sup>nd</sup> Aug<sup>r</sup> 1850  
 Character assigned J A 1 LD



© 2019

Certificate (if required)

Lloyd's Register  
 Foundation

LON 620 - 0025