

ANNUAL SURVEYS.

No. 12 Survey held at London Date July 20th 29 1850
on the Bg Balkan Master O. Skeman
Tonnage 112 Built at Liverpool When built 1849
By whom built _____ Owners Samson
Port belonging to Liverpool Destined Voyage Beirut &c
If Surveyed Afloat or in Dry Dock Fountain Dock

Last Survey, No. 9074 Port of Liverpool Classed A1

The present Condition of the

Decks	Treenails	Windlass and Capstan
Waterways	Breasthooks and Stemson	Pumps
Comings	Transoms, Pointers, and Crutches	Boats
Upper Deck Beams & Fastenings	Timbers of the Frame	Masts, Yards, &c.
Lower Deck Beams & Fastenings	Keelsons	Sails <u>well found</u>
Planksheers	Clamps and Shelves	Anchors No. of <u>3 B^m Steam & 1 Hodge</u>
Sheerstrakes	Ceiling	Cables <u>well found</u>
Topsides	Rudder	Hawsers and Warps
Wales	Copper <u>Y Metal</u> When put on <u>July 1850</u>	Standing & Running Rigging <u>good</u>
Plank (Bottom) and Counter		

General Observations and Opinion At the present time iron fallen over at the Wharf near London. Bridge has been shipped and the treenails and bolts drifted out on the port side (to allow her to drop down for her original sheer) from the after part of the mainmast to the fore part of the foremast, caulked from the keel to the gunwale. Several additional through bolts in the lower deck clamps, and resheathed with Y Metal over paper

Committee Minute 13th Aug 1850 now in a very efficient state and may retain her present class
Character assigned A1 for service
Spl Damage £4.4
Certificate (if required)

No. 423 Survey held at London Date August 2nd 1850
on the Bk Sir John Rae Rio Master Dyson
Tonnage 327 Built at London When built 1820
By whom built _____ Owners Meaning
Port belonging to London Destined Voyage S. Rish
If Surveyed Afloat or in Dry Dock Afloat

Last Survey, No. 15718 Port of London S.S. Classed A1 Astonsk

The present Condition of the

Decks	Treenails	Windlass and Capstan
Waterways	Breasthooks and Stemson	Pumps
Comings	Transoms, Pointers, and Crutches	Boats
Upper Deck Beams & Fastenings	Timbers of the Frame <u>good when seen</u>	Masts, Yards, &c.
Lower Deck Beams & Fastenings	Keelsons	Sails <u>well found</u>
Planksheers	Clamps and Shelves	Anchors No. of <u>3 B^m Steam & 2 Hodge</u>
Sheerstrakes	Ceiling	Cables <u>well found</u>
Topsides	Rudder	Hawsers and Warps
Wales	Copper <u>Y Metal</u> When put on <u>1840</u>	Standing & Running Rigging <u>good</u>
Plank (Bottom) and Counter		

General Observations and Opinion In the present year caulked from the copper overalls from her general good condition am of opinion she is fit for the safe conveyance of dry & perishable cargoes to & from all parts of the world and may continue as classed

Committee Minute 13th Aug 1850
Character assigned A1 for service
Certificate (if required)