

ANNUAL SURVEYS.

16243

No. 151 Survey held at London Date 9 July 1850
 on the Ship "Royal Albert" Master Stanlan
 Tonnage 550 Built at London When built 1844
 By whom built Wigram Owners Wigram
 Port belonging to London Destined Voyage Wigram's Dock
 If Surveyed Afloat or in Dry Dock in Wigram's Dock

Last Survey, No. 1497 Port of London Classed 12A1

The present Condition of the

| | | |
|-------------------------------|--|---|
| Decks | Treenails | Windlass and Capstan |
| Waterways | Breasthooks and Stemson | Pumps |
| Comings | Transoms, Pointers, and Crutches | Boats |
| Upper Deck Beams & Fastenings | Timbers of the Frame | Masts, Yards, &c. <u>New Mizen Mast</u> |
| Lower Deck Beams & Fastenings | Keelsons | Sails <u>out trashed</u> |
| Planksheers | Clamps and Shelves | Anchors No. of |
| Sheerstrakes | Ceiling | Cables |
| Topsides | Rudder | Hawsers and Warps |
| Wales | Copper <u>Ym</u> When put on <u>1849</u> | Standing & Running Rigging |

General Observations and Opinion,

Docked at present to inspect state of
Yellow Metal which has been exposed appears
in most efficient condition and may
continue as classed
 Committee Minute 30th Aug 1850
 Character assigned 12A1
W. H. H. H.
 Certificate (if required)

No. 153 Survey held at London Date 9 July 1850
 on the Ship Derbyshire Master Consett
 Tonnage 703 Built at London When built 1848
 By whom built Wigram Owners Wigram
 Port belonging to London Destined Voyage Wigram's Dock
 If Surveyed Afloat or in Dry Dock in Wigram's Dock

Last Survey, No. 14595 Port of London Classed 13A1

The present Condition of the

| | | |
|-------------------------------|--|-------------------------------|
| Decks | Treenails | Windlass and Capstan |
| Waterways <u>Caulked</u> | Breasthooks and Stemson | Pumps |
| Comings | Transoms, Pointers, and Crutches | Boats |
| Upper Deck Beams & Fastenings | Timbers of the Frame | Masts, Yards, &c. <u>will</u> |
| Lower Deck Beams & Fastenings | Keelsons | Sails <u>found</u> |
| Planksheers | Clamps and Shelves | Anchors No. of |
| Sheerstrakes | Ceiling | Cables |
| Topsides | Rudder | Hawsers and Warps |
| Wales | Copper <u>Ym</u> When put on <u>1848</u> | Standing & Running Rigging |

General Observations and Opinion,

Docked at present to inspect the state
of the Yellow Metal Sheathing which has been
exposed appears in most efficient
condition and may remain
 Committee Minute 30th Aug 1850
 Character assigned 13A1
W. H. H. H.
 Certificate (if required)