

ANNUAL SURVEYS.

10250

No. 39 Survey held at London Date Aug 20 1850
 on the B^t Acasta Master Robertson
 Tonnage 305 Built at Aberdeen When built 1845
 By whom built _____ Owners B Moir
 Port belonging to Aberdeen Destined Voyage Guylon
 If Surveyed Afloat or in Dry Dock In Princes Dry Dock

Last Survey, No. 15427 Port of London Classed 9 A 1
49

The present Condition of the

Decks	Treenails	Windlass and Capstan
Waterways } <u>good</u>	Breasthooks and Stemson	Pumps
Comings	Transoms, Pointers, and Crutches	Boats
Upper Deck Beams & Fastenings	Timbers of the Frame	Masts, Yards, &c.
Lower Deck Beams & Fastenings	Keelsons	Sails
Planksheers	Clamps and Shelves	Anchors No. of
Sheerstrakes	Ceiling	Cables
Topsides	Rudder	Hawsers and Warps
Wales	Copper <u>Yellow Metal</u> When put on <u>new</u>	Standing & Running Rigging
Plank (Bottom) and Counter	<u>on Felt</u>	

General Observations and Opinion,
Now done. The Yellow Metal Sheathing stripped off and renewed
upon Felt, the Ship hung in thous; Bottom and second Seam up
of Wales Caulked; the Metal extends to second Seam of Wales;
nearly all the in and out Bolts of Hold Beam Lodging knees renewed
with Metal in lieu of Iron; a False Keel of
added; a Pintle and Brace new of Metal
in lieu of Iron. She appears to be in good
condition eligible to remain as classed A 1
 Committee Minute 30 Sept 1850
 Character assigned A 1
recd J. M. J. A. Martin Certificate (if required)

No. 30 Survey held at London Date Aug 20 1850
 on the B^t Brazilian Master Thompson
 Tonnage 2341 Built at Liverpool When built 1824
 By whom built _____ Owners Clayton & Co
 Port belonging to Liverpool Destined Voyage _____
 If Surveyed Afloat or in Dry Dock In Fountain Dry Dock

Last Survey, No. 8865 Port of Liverpool Classed A 1
rest 47 0 40

The present Condition of the

Decks	Treenails	Windlass and Capstan
Waterways } <u>good</u>	Breasthooks and Stemson	Pumps
Comings	Transoms, Pointers, and Crutches	Boats
Upper Deck Beams & Fastenings	Timbers of the Frame	Masts, Yards, &c.
Lower Deck Beams & Fastenings	Keelsons	Sails
Planksheers	Clamps and Shelves	Anchors No. of
Sheerstrakes	Ceiling	Cables
Topsides	Rudder	Hawsers and Warps
Wales	Copper <u>Yellow Metal</u> When put on <u>new</u>	Standing & Running Rigging
Plank (Bottom) and Counter	<u>on Felt</u>	

General Observations and Opinion,
Now done. The Yellow Metal Sheathing stripped off and
renewed upon Felt; Wales and Bottom Caulked; a Plank
of Wale in Midship on the Port side replaced with new of Pitch pine
the original being warped; a False Stern Post
added, and the whole of Ceiling scraped
light one new middle piece to a Deck Beam
She appears to be in good condition, eligible
to remain as classed A 1
 Committee Minute 30 Sept 1850
 Character assigned A 1
recd J. M. J. A. Martin Certificate (if required)