

# ANNUAL SURVEYS.

10250

No. 39 Survey held at London Date Aug 20 1850  
 on the B<sup>t</sup> Acasta Master Robertson  
 Tonnage 305 Built at Aberdeen When built 1845  
 By whom built  Owners B Moir  
 Port belonging to Aberdeen Destined Voyage Guylon  
 If Surveyed Afloat or in Dry Dock In Princes Dry Dock

Last Survey, No. 15427 Port of London Classed 9 A 1  
49

The present Condition of the

Decks	Treenails	Windlass and Capstan
Waterways } <u>good</u>	Breasthooks and Stemson	Pumps
Comings	Transoms, Pointers, and Crutches	Boats
Upper Deck Beams & Fastenings	Timbers of the Frame	Masts, Yards, &c.
Lower Deck Beams & Fastenings	Keelsons	Sails
Planksheers	Clamps and Shelves	Anchors No. of
Sheerstrakes	Ceiling	Cables
Topsides	Rudder	Hawsers and Warps
Wales	Copper <u>Yellow Metal</u> When put on <u>new</u>	Standing & Running Rigging
Plank (Bottom) and Counter	<u>on Felt</u>	

General Observations and Opinion,  
Now done. The Yellow Metal Sheathing stripped off and renewed  
upon Felt, the Ship hung in thous; Bottom and second Seam up  
of Wales Caulked; the Metal extends to second Seam of Wales;  
nearly all the in and out Bolts of Hold Beam Lodging knees renewed  
with Metal in lieu of Iron; a False Keel of  
added; a Pintle and Brace new of Metal  
in lieu of Iron. She appears to be in good  
condition eligible to remain as classed A 1  
rec'd P. M.  
J. A. Martin Certificate (if required)

No. 30 Survey held at London Date Aug 20 1850  
 on the B<sup>t</sup> Brazilian Master Thompson  
 Tonnage 2341 Built at Liverpool When built 1824  
 By whom built  Owners Clayton & Co  
 Port belonging to Liverpool Destined Voyage   
 If Surveyed Afloat or in Dry Dock In Fountain Dry Dock

Last Survey, No. 8865 Port of Liverpool Classed A 1  
rest 47 0 40

The present Condition of the

Decks	Treenails	Windlass and Capstan
Waterways } <u>good</u>	Breasthooks and Stemson	Pumps
Comings	Transoms, Pointers, and Crutches	Boats
Upper Deck Beams & Fastenings	Timbers of the Frame	Masts, Yards, &c.
Lower Deck Beams & Fastenings	Keelsons	Sails
Planksheers	Clamps and Shelves	Anchors No. of
Sheerstrakes	Ceiling	Cables
Topsides	Rudder	Hawsers and Warps
Wales	Copper <u>Yellow Metal</u> When put on <u>new</u>	Standing & Running Rigging
Plank (Bottom) and Counter	<u>on Felt</u>	

General Observations and Opinion,  
Now done. The Yellow Metal Sheathing stripped off and  
renewed upon Felt; Wales and Bottom Caulked; a Plank  
of Wale in Midship on the Port side replaced with new of Pitch pine  
the original being warped; a False Stern Post  
added, and the whole of Ceiling scraped  
light one new middle piece to a Deck Beam  
She appears to be in good condition, eligible  
to remain as classed A 1  
rec'd P. M.  
J. A. Martin Certificate (if required)