

ANNUAL SURVEYS.

No. 326

on the

Survey held at

London

Date

April 23

May 3

1851

Master

Furness

Tonnage

871

Built at

London

When built

1837

By whom built

Green

Owners

Green

Port belonging to

London

Destined Voyage

India

If Surveyed Afloat or in Dry Dock

Afloat & Dry Dock

12

Last Survey, No. 10125 Port of

London

Classed

Low 4 A 1

The present Condition of the

Decks

Good

Treenails

Good

Windlass and Capstan

Efficient

Waterways

Breasthooks and Stemson

Pumps

As

Comings

Transoms, Pointers, and Crutches

Boats

As

Upper Deck Beams & Fastenings

Secured

Timbers of the Frame

Masts, Yards, &c.

As

Lower Deck Beams & Fastenings

As

Keelsons

Sails

As

Planksheers

As

Clamps and Shelves

Anchors

No. of 3. 1. 1

As

Sheerstrakes

As

Ceiling

Cables

As

Topsides

As

Rudder

Hawsers and Warps

As

Wales

As

Copper

Metals

When put on

1850

Standing & Running Rigging

As

Plank (Bottom) and Counter

As

General Observations and Opinion,

Caulked from the Copper up and overhauled is in good and efficient condition and eligible for service as ^{closed} Fourway

Committee Minute

20 May 1851

Character assigned

Low 4 A 1

Certificate (if required)

No. 112

on the

Survey held at

London

Date

April 23 & May 1851

Master

Parish

Tonnage

1014

Built at

London

When built

1844

By whom built

Green

Owners

Green

Port belonging to

London

Destined Voyage

Madras, Calcutta

If Surveyed Afloat or in Dry Dock

Dry Dock

Last Survey, No. 15186 Port of

London

Classed

12 A 1

The present Condition of the

Decks

Good

Treenails

Good

Windlass and Capstan

Efficient

Waterways

Breasthooks and Stemson

Pumps

As

Comings

Transoms, Pointers, and Crutches

Boats

As

Upper Deck Beams & Fastenings

Secured

Timbers of the Frame

Masts, Yards, &c.

New Main Mast As

Lower Deck Beams & Fastenings

As

Keelsons

Sails

As

Planksheers

Good

Clamps and Shelves

Anchors

No. of 3. 1. 1

As

Sheerstrakes

As

Ceiling

Cables

As

Topsides

As

Rudder

Hawsers and Warps

As

Wales

As

Copper

Metals

When put on

1849

Standing & Running Rigging

As

Plank (Bottom) and Counter

As

General Observations and Opinion,

Additional bolts in Scarp of Stelson Caulked from the Copper up and generally overhauled in Hull & equipment is in good and efficient condition and may remain as ^{closed} Fourway

Committee Minute

20 May 1851

Character assigned

12 A 1

Certificate (if required)