

ANNUAL SURVEYS.

10799

No. ⁵³ on the 13th Navarino Survey held at London Date May 13th 1851
 Tonnage 493 Built at Cochin Master R. Paige
 By whom built _____ Owners G. Marshall
 Port belonging to London Destined Voyage Australia
 If Surveyed Afloat or in Dry Dock In Prince's Dry Dock

Last Survey, No. 11082 Port of London Classed *A
S.S. 40 4 mo 50

The present Condition of the

Decks	Treenails	Windlass and Capstan
Waterways } <u>Good</u>	Breasthooks and Stemson	Pumps
Comings	Transoms, Pointers, and Crutches } <u>Good where seen</u>	Boats
Upper Deck Beams & Fastenings	Timbers of the Frame	Masts, Yards, &c. } <u>In good order</u>
Lower Deck Beams & Fastenings } <u>all where seen</u>	Keelsons	Sails } <u>and sufficient</u>
Planksheers	Clamps and Shelves	Anchors No. of
Sheerstrakes	Ceiling	Cables
Topsides	Rudder	Hawsers and Warps
Wales	Copper } <u>metal</u> When put on <u>now new</u>	Standing & Running Rigging
Plank (Bottom) and Counter		

General Observations and Opinion

Now done. Yellow metal sheathing stripped off and renewed upon base doubling throughout the bottom, and upon the whole of Wales except upper stache; Bottom caulked. The appears fit for the safe conveyance of dry and perishable cargoes to and from all parts. Committee Minute 20th May 1851 Character assigned A Approved G. M. J. Martin Certificate (if required)

No. ⁵ on the 1st Conqueror Survey held at London Date May 16 1851
 Tonnage 407 Built at Aberdeen Master G. Rennie
 By whom built _____ Owners Rennie & Co.
 Port belonging to Aberdeen Destined Voyage Calcutta
 If Surveyed Afloat or in Dry Dock In Lavender Dry Dock

Last Survey, No. 1480 Port of Aberdeen Classed 12 A
5 mo 50

The present Condition of the

Decks	Treenails	Windlass and Capstan
Waterways } <u>Good</u>	Breasthooks and Stemson	Pumps
Comings	Transoms, Pointers, and Crutches } <u>Good where seen</u>	Boats
Upper Deck Beams & Fastenings	Timbers of the Frame	Masts, Yards, &c. } <u>In good order</u>
Lower Deck Beams & Fastenings } <u>all where seen</u>	Keelsons	Sails } <u>and sufficient</u>
Planksheers	Clamps and Shelves	Anchors No. of
Sheerstrakes	Ceiling	Cables
Topsides	Rudder	Hawsers and Warps
Wales	Copper } <u>metal</u> When put on <u>1850</u>	Standing & Running Rigging
Plank (Bottom) and Counter		

General Observations and Opinion

Now done. The three upper staches of Yellow metal sheathing stripped off and renewed upon Felt extending from fore part of fore to after part of main chain the planing brightened in way of the above to find a leak and caulked at that part. The appears to be in good condition eligible to remain classed A. Committee Minute 20th May 1851 Character assigned 12 A Approved G. M. J. Martin Certificate (if required)