

ANNUAL SURVEYS.

16889

No. 18 Survey held at London Date 15 26 May 1857
 on the Ship Symmetry Master Richardson
 Tonnage 382 Built at Scarbro When built 1823
 By whom built _____ Owners Wm Tindall
 Port belonging to London Destined Voyage Ceylon
 If Surveyed Afloat or in Dry Dock in Mr Tindalls Dock & Warehouse

Head 3 July

Last Survey, No. 15799 Port of London Classed * A 1 S.S. 50

The present Condition of the

Decks	Treenails	Windlass and Capstan <u>New Ball & Carpenters</u>
Waterways	Breasthooks and Stemson	<u>Refitted</u>
Comings	Transoms, Pointers, and Crutches	Pumps <u>Good</u>
Upper Deck Beams & Fastenings	Timbers of the Frame	Boats <u>Three</u>
Lower Deck Beams & Fastenings	Keelsons	Masts, Yards, &c. <u>New four & main masts</u>
Planksheers	Clamps and Shelves	Sails <u>Sufficient</u>
Sheerstrakes	Ceiling	Anchors No. of <u>3 1 2</u>
Topsides	Rudder	Cables <u>Sufficient</u>
Wales	Copper <u>ym</u> When put on <u>May</u>	Hawsers and Warps <u>Do</u>
Plank (Bottom) and Counter		Standing & Running Rigging <u>Do</u>

General Observations and Opinion, at present bottom stripped and doubly
Caulked and sheathed with yellow metal the
windlass unburnt & two new upper & beams fitted
under windlass & new bits new four & main masts
 Committee Minute 4th July 1857 Shipped appears fit for the safe
 Character assigned A 1 After conveyance of dry & perishable
and 2000 cargo to & from a Certificate (if required)
of the goods & cargo to be shipped as

No. _____ Survey held at London Date 18 57
 on the _____ Master _____
 Tonnage _____ Built at _____ When built _____
 By whom built _____ Owners _____
 Port belonging to _____ Destined Voyage _____
 If Surveyed Afloat or in Dry Dock _____

Last Survey, No. _____ Port of _____ Classed _____

The present Condition of the

Decks	Treenails	Windlass and Capstan
Waterways	Breasthooks and Stemson	Pumps
Comings	Transoms, Pointers, and Crutches	Boats
Upper Deck Beams & Fastenings	Timbers of the Frame	Masts, Yards, &c.
Lower Deck Beams & Fastenings	Keelsons	Sails
Planksheers	Clamps and Shelves	Anchors No. of
Sheerstrakes	Ceiling	Cables
Topsides	Rudder	Hawsers and Warps
Wales	Copper	Standing & Running Rigging
Plank (Bottom) and Counter	When put on	

General Observations and Opinion,

Committee Minute _____ 18
 Character assigned _____