

ANNUAL SURVEYS.

No. 87 Survey held at London Date June 30 1850
 on the Bk Water Lily Master Shart
 Tonnage 262 Built at Southampton When built 1824
 By whom built _____ Owners J Dawson
 Port belonging to London Destined Voyage Jamaica
 If Surveyed Afloat or in Dry Dock Simckely Dock
 ND & T Sds 41 S/ps 49

Last Survey, No. 15415 Port of London SS 1849 Classed *E, 1st class
 expunged

The present Condition of the

Decks	Treenails	Windlass and Capstan
Waterways	Breasthooks and Stemson	Pumps
Comings	Transoms, Pointers, and Crutches	Boats
Upper Deck Beams & Fastenings	Timbers of the Frame	Masts, Yards, &c.
Lower Deck Beams & Fastenings	Keelsons	Sails
Planksheers	Clamps and Shelves	Anchors No. of
Sheerstrakes	Ceiling	Cables
Topsides	Rudder	Hawsers and Warps
Wales	Copper	Standing & Running Rigging
Plank (Bottom) and Counter	When put on <u>1847</u>	

General Observations and Opinion, This vessel is in a very efficient state, & fit for the safe conveyance of dry & perishable cargoes to & from all parts of the world & may continue as classed *E, 1st class

Committee Minute 4th July 1850
 Character assigned A, 1st class
 Certificate (if required)

No. 399 Survey held at London Date June 30 1857
 on the Bk Port Stanley Master Thomas
 Tonnage 300 Built at New Brunswick When built 1841
 By whom built _____ Owners Mitchison
 Port belonging to London Destined Voyage Quebec
 If Surveyed Afloat or in Dry Dock Landen Dock
 pt F & S. 49 W. pt F & S. 49

Last Survey, No. 15371 Port of London SS 1846 4/4 Classed *E, 1st class
 expunged

The present Condition of the

Decks	Treenails	Windlass and Capstan
Waterways	Breasthooks and Stemson	Pumps
Comings	Transoms, Pointers, and Crutches	Boats
Upper Deck Beams & Fastenings	Timbers of the Frame	Masts, Yards, &c.
Lower Deck Beams & Fastenings	Keelsons	Sails
Planksheers	Clamps and Shelves	Anchors No. of
Sheerstrakes	Ceiling	Cables
Topsides	Rudder	Hawsers and Warps
Wales	Copper	Standing & Running Rigging
Plank (Bottom) and Counter	When put on <u>1841</u>	

General Observations and Opinion, Notice has been left to open at the turn of the ridge, which the owner refuses to do, bottom shipped & sawed, opinion as the state of the frame cannot be seen her
4th July 1857 character should be expunged

Committee Minute 4th July 1857
 Character assigned Second Survey
 Certificate (if required)