

REPORT of SURVEY for REPAIRS.

16920

[Signature]
Recd 27 July

No.

Survey held at

London

Date

July 11th

1851

on the

Bk Tigris

Master

Tonnage

370

Built at

Sunderland

When built

1851

By whom built

Owners

P Tindall

Port belonging to

London

Destined Voyage

West Indies

If Surveyed Afloat or in Dry Dock

West India Dock

Last Survey, No.

4521

Port

Sunderland

Classed

A1

REPAIRS

At the present time a lower deck of waterway of Dantzic Oak & pair of Iron knee riders, one abreast of the Mainmast, one abreast of Foremast and one under the cabin deck, an Iron clutch over the transoms, six pair of Iron knees to the upper deck beams & one pair of staple standards, caulked from the keel to the Gunwale and sheathed with Yellow Amul over felt,

Present Condition of the

Decks

Waterways

Comings

Upper Deck Beams & Fastenings

Lower Deck Beams & Fastenings

Planksheers

Sheerstrakes

Topsides

Wales

Plank (Bottom) and Counter

Treenails

Breasthooks and Stenson

Transoms, Pointers, and Cruches

Timbers of the Frame

Keelsons

Clamps and Shelves

Ceiling

Rudder

Copper

When put on 1851

Windlass and Capstan

Pumps

Boats

Masts, Yards, &c.

Sails

Anchors No. of 3 Bower Stm & Kedge

Cables

Hawsers and Warps

Standing & Running Rigging

General Observations and Opinion,

Appears in all respects in a good & efficient state to retain her present class

[Signature]

The Amount of Fee.....£ : : is received by me,

Special..... : :

Certificate (if required) : :

Committee's Minute

18th July 1851

Character assigned

[Signature]



© 2019

Lloyd's Register Foundation

LON 630-0307