

REPORT of SURVEY for REPAIRS.

& Change of Owner

No. 165 Survey held at London Date July 10 & 16 1857
on the Bk Reliance Master D. Hambro

Tonnage 242 Built at Peterhead When built 1840

By whom built _____ Owners Hambro

Port belonging to Greenock Destined Voyage Sandwich Isles

If Surveyed Afloat or in Dry Dock West India Dock

Last Survey, No. 2,182 Port Glyde Pen 1840 Classed 3 A1

REPAIRS two planks next the renewed on the starboard side & one on the Port side of Decks caulked

Bottom has been examined in Doroons ship

Present Condition of the

| | | |
|-------------------------------------------|---------------------------------------------|------------------------------------------------|
| Decks <u>Good</u> | Treenails _____ | Windlass and Capstan <u>good</u> |
| Waterways <u>Do</u> | Breasthooks and Stemson <u>good</u> | Pumps <u>Do</u> |
| Comings <u>Do</u> | Transoms, Pointers, and Crutches <u>Do</u> | Boats <u>Do</u> |
| Upper Deck Beams & Fastenings <u>good</u> | Timbers of the Frame <u>good where seen</u> | Masts, Yards, &c. <u>Do</u> |
| Lower Deck Beams & Fastenings <u>Do</u> | Keelsons <u>Do</u> | Sails <u>well found</u> |
| Planksheers <u>good</u> | Clamps and Shelves <u>Do</u> | Anchors No. of <u>3 Bows Shear & Kedge</u> |
| Sheerstrakes <u>Do</u> | Ceiling <u>Do</u> | Cables <u>well found</u> |
| Topsides <u>Do</u> | Rudder <u>Do</u> | Hawsers and Warps <u>Do</u> |
| Wales <u>Do</u> | Copper _____ | Standing & Running Rigging <u>good</u> |
| Plank (Bottom) and Counter <u>good</u> | When put on <u>1849</u> | |

General Observations and Opinion, I am of opinion this vessel is in good condition to retain her present character

The Amount of Fee.....£ / : : is received by me,

Special..... : :

Certificate (if required) : 10 : -

Committee's Minute 22nd July 1857

Character assigned Class 3 A1



© 2019

Lloyd's Register Foundation

LON 630-0310