

REPORT of SURVEY for REPAIRS.

16974

No. 457 Survey held at London Date July 29 to August 5th 1857
 on the Bk Andromache Master M. Passmore
 Tonnage 460 Built at Scarb'g When built 1820
 By whom built _____ Owners Tebbut & Co
 Port belonging to London Destined Voyage Port Philip
 If Surveyed Afloat or in Dry Dock Linekiln Dock

Last Survey, No. 16210 Port London Restored 1845 Classed 10
7A1

REPAIRS From damage having been on shore at Port Adelaide, yellow metal shipped
off, new false keel, three rough tree stations, hung in shores, caulked from
the keel to the waterway seam & sheathed with yellow metal on both
not of damage one pair of iron knee-riders from the midship hold down to the
floor, keelnails examined & a general overhaul

Present Condition of the

| | | |
|---|--|---|
| Decks <u>good</u> | Treenails <u>good</u> | Windlass and Capstan <u>good</u> |
| Waterways <u>Do</u> | Breasthooks and Stenson <u>Do</u> | Pumps <u>Do</u> |
| Comings <u>Do</u> | Transoms, Pointers, and Crutches <u>Do</u> | Boats <u>Do</u> |
| Upper Deck Beams & Fastenings <u>Do</u> | Timbers of the Frame <u>good where seen</u> | Masts, Yards, &c. <u>Do</u> |
| Lower Deck Beams & Fastenings <u>Do</u> | Keelsons <u>good</u> | Sails <u>well found</u> |
| Planksheers <u>good</u> | Clamps and Shells <u>Do</u> | Anchors No. of <u>3 Bower Iron & 2 Hedges</u> |
| Sheerstrakes <u>Do</u> | Ceiling <u>Do</u> | Cables <u>well found</u> |
| Topsides <u>Do</u> | Rudder <u>Do</u> | Hawsers and Warps <u>Do</u> |
| Wales <u>Do</u> | Copper <u>yellow metal</u> When put on <u>Aug 1857</u> | Standing & Running Rigging <u>good</u> |
| Plank (Bottom) and Counter <u>good</u> | | |

General Observations and Opinion, From her good & efficient state am of opinion she may
retain her present class

R. W. M. Wilson

The Amount of Fee.....£ : : is received by me,

Special..... 4 : 4 : 0

Certificate (if required) : :

Committee's Minute 12th Aug 1857

Character assigned Rest 7th



© 2019

Lloyd's Register
Foundation

LON 630-0361