

ANNUAL SURVEYS.

th 16978

No. 87 Survey held at London Date August 7 1851
 on the Bk Waterlily Master Greke
 Tonnage 262 Built at Southampton When built 1824
 By whom built Owners J Dawson
 Port belonging to London Destined Voyage Jamaica
 If Surveyed Afloat or in Dry Dock Afloat

Recd 15 Aug

Last Survey, No. 14896 Port of London 1849 SS Classed *A.1 Stenisk

The present Condition of the

Decks <u>Good</u>	Treenails <u> </u>	Windlass and Capstan <u>good</u>
Waterways <u>Do</u>	Breasthooks and Stemson <u>good</u>	Pumps <u>Do</u>
Comings <u>Do</u>	Transoms, Pointers, and Crutches <u>Do</u>	Boats <u>Do</u>
Upper Deck Beams & Fastenings <u>good</u>	Timbers of the Frame <u>Do</u>	Masts, Yards, &c. <u>Do</u>
Lower Deck Beams & Fastenings <u>Do</u>	Keelsons <u>good</u>	Sails <u>well found</u>
Planksheers <u> </u>	Clamps and Shelves <u>Do</u>	Anchors No. of <u>3 Bower Stm & 1 Hedge</u>
Sheerstrakes <u> </u>	Ceiling <u>Do</u>	Cables <u>well found</u>
Topsides <u>good</u>	Rudder <u>Do</u>	Hawsers and Warps <u>Do</u>
Wales <u> </u>	Copper <u>Y.M.</u>	Standing & Running Rigging <u>good</u>
Plank (Bottom) and Counter <u> </u>	<u>1847</u>	

General Observations and Opinion, This vessel is in a very good condition for the safe conveyance of dry & perishable cargoes to & from all parts of the world & may continue as classed A.1 Stenisk

Committee Minute 15th Aug 1845

Character assigned A.1 Stenisk

A.1 Stenisk

Certificate (if required)

No. 180 Survey held at London Date August 5 to 11 1851
 on the Bk Castle Lachlan Master G Bruce
 Tonnage 435 Built at Glasgow When built 1811
 By whom built Owners J Dawson & Co
 Port belonging to London Destined Voyage Jamaica
 If Surveyed Afloat or in Dry Dock Lincoln Dock

Last Survey, No. 14286 Port of London SS 49 Classed *A.1 Stenisk

The present Condition of the

Decks <u>Good</u>	Treenails <u>good</u>	Windlass and Capstan <u>good</u>
Waterways <u>Do</u>	Breasthooks and Stemson <u>Do</u>	Pumps <u>Do</u>
Comings <u>Do</u>	Transoms, Pointers, and Crutches <u>Do</u>	Boats <u>Do</u>
Upper Deck Beams & Fastenings <u>good & firm</u>	Timbers of the Frame <u>good & when seen</u>	Masts, Yards, &c. <u>Do</u>
Lower Deck Beams & Fastenings <u>Do</u>	Keelsons <u>Good</u>	Sails <u>well found</u>
Planksheers <u> </u>	Clamps and Shelves <u>Do</u>	Anchors No. of <u>3 Bower Stm & 2 Hedges</u>
Sheerstrakes <u> </u>	Ceiling <u>Do</u>	Cables <u>well found</u>
Topsides <u>good</u>	Rudder <u>Do</u>	Hawsers and Warps <u>Do</u>
Wales <u> </u>	Copper <u>F.S. & C. 145 pt 49</u>	Standing & Running Rigging <u>good</u>
Plank (Bottom) and Counter <u> </u>		

General Observations and Opinion, Copper patched with about 100 sheets & is in a very efficient state for the safe conveyance of dry & perishable cargoes to & from all parts of the world and may continue as classed A.1 Stenisk

Committee Minute 15th Aug 1845

Character assigned A.1 Stenisk

A.1 Stenisk

Certificate (if required)