

REPORT of SURVEY for REPAIRS.

Change of Owners

No. 598 Survey held at London Date Sept 11 & 22 1857
 on the S Emperor of China Master Daniell
 Tonnage 416 Built at Biddford When built 1847
 By whom built Owners Daniell & Co
 Port belonging to London Destined Voyage Shanghai
 If Surveyed Afloat or in Dry Dock Fletcher's Dock & St Kath Dock

Last Survey, No. 425 Port of Swansea Classed 12 A1

REPAIRS Bottom examined in dry dock,

Present Condition of the

| | | |
|-------------------------------|--|---|
| Decks | Treenails <u>good</u> | Windlass and Capstan <u>good</u> |
| Waterways | Breasthooks and Stemson <u>Do</u> | Pumps <u>Do</u> |
| Comings | Transoms, Pointers, and Crutches <u>Do</u> | Boats <u>Do</u> |
| Upper Deck Beams & Fastenings | Timbers of the Frame <u>good when seen</u> | Masts, Yards, &c. <u>Do</u> |
| Lower Deck Beams & Fastenings | Keelsons <u>Do</u> | Sails <u>well found</u> |
| Planksheers | Clamps and Shelves <u>Do</u> | Anchors No. of <u>3 Bower Stn & Kedge</u> |
| Sheerstrakes | Ceiling <u>Do</u> | Cables <u>well found</u> |
| Topsides | Rudder <u>Do</u> | Hawsers and Warps <u>Do</u> |
| Wales | Copper <u>Y.M.</u> When put on <u>1850</u> | Standing & Running Rigging <u>good</u> |
| Plank (Bottom) and Counter | | |

General Observations and Opinion It is in all respects in a very efficient state to retain
in present class

The Amount of Fee.....£ 2 : — : — is received by me, 30/10/57

Special.....

Certificate (if required).....

Committee's Minute 31st Oct 1857

Character assigned 12 A1



© 2019
 Lloyd's Register
 Foundation