

REPORT of SURVEY for REPAIRS.

Change of owners

Rec 2/10/57

17136

No. *86* Survey held at *London* Date *October 6th* 18 *57*

on the *SS "General Sale"* Master *A Thompson*

Tonnage *357* Built at *Sunderland* When built *1843*

By whom built *406* Owners *Capt*

Port belonging to *London* Destined Voyage *Spain Robert Town*

If Surveyed Afloat or in Dry Dock *At Katherine Dock had been in Docks in Ship*

Last Survey, No. *9532* Port *Lpool* Classed *9 A 1*

REPAIRS

Present Condition of the

Decks <i>Good</i>	Treenails <i>Good</i>	Windlass and Capstan <i>efficient</i>
Waterways <i>do</i>	Breasthooks and Stemson <i>do</i>	Pumps <i>do</i>
Comings <i>do</i>	Transoms, Pointers, and Crutches <i>do</i>	Boats <i>do</i>
Upper Deck Beams & Fastenings <i>Secure</i>	Timbers of the Frame <i>When seen do</i>	Masts, Yards, &c. <i>do</i>
Lower Deck Beams & Fastenings <i>do</i>	Keelsons <i>do</i>	Sails <i>do</i>
Planksheers <i>Good</i>	Clamps and Shelves <i>do</i>	Anchors No. of <i>3 B 1 S 1 4</i> <i>do</i>
Sheerstrakes <i>do</i>	Ceiling <i>do</i>	Cables <i>do</i>
Topsides <i>partially do</i>	Rudder <i>do</i>	Hawsers and Warps <i>do</i>
Wales <i>& Caulked do</i>	Copper <i>When put on 1849</i>	Standing & Running Rigging <i>do</i>
Plank (Bottom) and Counter <i>do</i>	<i>now Patched</i>	

General Observations and Opinion,

She appears in good and efficient condition and ought to remain as classed

The Amount of Fee.....£ *2* : : is received by me,

Special..... : : }

Certificate (if required) : *10* : }

Committee's Minute *4th Nov 1857*

Character assigned *9 A 1*



© 2019
Lloyd's Register
Foundation