

REPORT of SURVEY for REPAIRS.

17140

Reception

No. 99 Survey held at London Date October 30th 1857
 on the M^r "Marchioness of Cilla" Master M^r Fudge
 Tonnage 299 Built at Ayr When built 1847
 By whom built 1335 Owners Storn
 Port belonging to Ayr Destined Voyage Dumfries
 If Surveyed Afloat or in Dry Dock Dry Dock

Last Survey, No. 2319 Port Clyde Classed 6 A
capit

REPAIRS

*A the present time 2 new planks in the ceiling
 forward, the iron bar strokes through bolted
 curved from the keel to the wales and sheathed
 with yellow metal upon dry paper,*

Present Condition of the

Decks <u>Good</u>	Treenails <u>Good</u>	Windlass and Capstan <u>efficient</u>
Waterways <u>—</u>	Breasthooks and Stemson <u>—</u>	Pumps <u>do</u>
Comings <u>—</u>	Transoms, Pointers, and Crutches <u>—</u>	Boats <u>do</u>
Upper Deck Beams & Fastenings <u>Storn</u>	Timbers of the Frame <u>Whinsea</u>	Masts, Yards, &c. <u>do</u>
Lower Deck Beams & Fastenings <u>do</u>	Keelsons <u>—</u>	Sails <u>do</u>
Planksheers <u>Good</u>	Clamps and Shelves <u>—</u>	Anchors No. of <u>2 BISH</u> <u>do</u>
Sheerstrakes <u>do</u>	Ceiling <u>—</u>	Cables <u>do</u>
Topsides <u>do</u>	Rudder <u>—</u>	Hawsers and Warps <u>do</u>
Wales <u>do</u>	Copper <u>Yellow Metal</u> When put on <u>1857</u>	Standing & Running Rigging <u>do</u>
Plank (Bottom) and Counter <u>do</u>		

General Observations and Opinion,

*She is in an efficient condition and
 eligible to be reclassified, 6 A*

J. Fourtenay

The Amount of Fee.....£ 1 : — : — is received by me,

Special..... : : } *R. G. G. G.*

Certificate (if required) : 10 :

Committee's Minute 7th Nov 1857

Character assigned 6 A 1

Storn 1/2



© 2019

Lloyd's Register
 Foundation

LON631-0098