

REPORT of SURVEY for REPAIRS.

17157

Revised

No. 469 on the Bk Ruckers Survey held at London Date Oct 21st to 24th 1857
 Tonnage 329 Built at London When built 1829
 By whom built _____ Owners Popplewell
 Port belonging to London Destined Voyage St Vincent
 If Surveyed Afloat or in Dry Dock Regents Dock

Last Survey, No. 18795 Port London Rest 41-8 Ton 1049 Classed 3 A1

REPAIRS Shipped, hung, upper course of bottom sheathed y shakes over felt, caulked from the keel to the wales and sheathed with yellow metal over felt, upper course of bottom re-nailed, several bolts driven out for examination and a general overhaul

Present Condition of the

Decks	Treenails	Windlass and Capstan
Waterways	Breasthooks and Stemson	Pumps
Comings	Transoms, Pointers, and Crutches	Boats
Upper Deck Beams & Fastenings	Timbers of the Frame	Masts, Yards, &c.
Lower Deck Beams & Fastenings	Keelsons	Sails
Planksheers	Clamps and Shelves	Anchors
Sheerstrakes	Ceiling	Cables
Topsides	Rudder	Hawsers and Warps
Wales	Copper	Standing & Running Rigging
Plank (Bottom) and Counter		

General Observations and Opinion, Is in a very efficient state & may continue her present class


The Amount of Fee.....£ 2 : - : - is received by me, [Signature]

Special..... : : -

Certificate (if required) : : -

Committee's Minute 14th Nov 1857

Character assigned Cu P. 3 A 1



© 2019
Lloyd's Register
Foundation

LON631-0105