

ANNUAL SURVEYS.

17180

No. 65 Survey held at London Date October 21 1857
 on the Sch "Salome" Master Porter
 Tonnage 120 Built at Dartmouth When built 1834
 By whom built " " Owners Varmer
 Port belonging to Dartmouth Destined Voyage Straits
 If Surveyed Afloat or in Dry Dock at Katherin Dock

Does not appear to have sailed to a foreign port
 not cleared outwards

Last Survey, No. 1172 Port of Dartmouth Classified FI S.S. 48
 C 3 50

The present Condition of the

Decks <u>Not in very good condition</u>	Treenails <u>When seen good</u>	Windlass and Capstan <u>efficient</u>
Waterways <u>good</u>	Breasthooks and Stemson <u>do</u>	Pumps <u>do</u>
Comings <u>"</u>	Transoms, Pointers, and Crutches <u>do</u>	Boats <u>do</u>
Upper Deck Beams & Fastenings <u>Upper 14 ft</u>	Timbers of the Frame <u>When seen do</u>	Masts, Yards, &c. <u>do</u>
Lower Deck Beams & Fastenings <u>"</u>	Keelsons <u>do</u>	Sails <u>do</u>
Plank sheers <u>Good</u>	Clamps and Shelves <u>do</u>	Anchors No. of <u>2/1/1</u> <u>do</u>
Sheerstrakes <u>"</u>	Ceiling <u>do</u>	Cables <u>do</u>
Topsides <u>"</u>	Rudder <u>do</u>	Hawsers and Warps <u>do</u>
Wales <u>"</u>	Copper <u>"</u> When put on <u>"</u>	Standing & Running Rigging <u>do</u>
Plank (Bottom) and Counter <u>"</u>		

General Observations and Opinion, Requested some planks to be shifted in the deck 2 pairs of Iron knees to be put to the deck beams and the caulking of the sheerstrakes plank sheers to be examined and caulked. In opinion she has sailed without

Committee Minute 25th Nov 1857
2nd Lieut Army those repairs
 Character assigned Write of Officer Hartney
As 25th Nov Certificate (if required)

No. 159 Survey held at London Date Oct 21 1857
 on the Mr Writ Master Collie
 Tonnage 374 Built at Aberdeen When built 1848
 By whom built 315 Owners Anderson
 Port belonging to Aberdeen Destined Voyage Alyra Bay
 If Surveyed Afloat or in Dry Dock London Dock

Last Survey, No. 15542 Port of London Classified GA
 49

The present Condition of the

Decks <u>Good</u>	Treenails <u>Good</u>	Windlass and Capstan <u>efficient</u>
Waterways <u>"</u>	Breasthooks and Stemson <u>"</u>	Pumps <u>"</u>
Comings <u>"</u>	Transoms, Pointers, and Crutches <u>"</u>	Boats <u>"</u>
Upper Deck Beams & Fastenings <u>Seen</u>	Timbers of the Frame <u>"</u>	Masts, Yards, &c. <u>"</u>
Lower Deck Beams & Fastenings <u>do</u>	Keelsons <u>"</u>	Sails <u>"</u>
Plank sheers <u>Good</u>	Clamps and Shelves <u>"</u>	Anchors No. of <u>2/1/1</u> <u>"</u>
Sheerstrakes <u>"</u>	Ceiling <u>"</u>	Cables <u>"</u>
Topsides <u>"</u>	Rudder <u>"</u>	Hawsers and Warps <u>"</u>
Wales <u>"</u>	Copper <u>"</u> When put on <u>1846</u>	Standing & Running Rigging <u>"</u>
Plank (Bottom) and Counter <u>"</u>		

General Observations and Opinion,

She is in good condition and suitable to us as a vessel

Committee Minute 25th Nov 1857
 Character assigned GA

© 2019
 Lloyd's Register Foundation
 Certificate (if required)
 LON631-0135