

REPORT of SURVEY for REPAIRS.

No. 74 Survey held at London Date January 2 1852
on the S Malabar Master E. Moakes
Tonnage 647 Built at London When built 1834
By whom built R. Green Owners R. Green
Port belonging to London Destined Voyage Cape & Madras
If Surveyed Afloat or in Dry Dock Greens Lower Dock

Last Survey, No. *15-133* Port *London* Restored *1848* Classed *12* } *A1*

REPAIRS Bottom stripped, hung in shores, raulked from the keel to ⁴⁹ the gunwale, sheathed with inch boards on the bottom ^{over} ~~from~~ the keel to the wales, and with Yellow Metal —

Present Condition of the

Decks	Treenails	Windlass and Capstan
Waterways	Breasthooks and Stemson	Pumps
Comings	Transoms, Pointers, and Crutches	Boats
Upper Deck Beams & Fastenings	Timbers of the Frame	Masts, Yards, &c.
Lower Deck Beams & Fastenings	Keelsons	Sails
Planksheers	Clamps and Shelves	Anchors
Sheerstrakes	Ceiling	Cables
Topsides	Rudder	Hawsers and Warps
Wales	Copper	Standing & Running Rigging
Plank (Bottom) and Counter	When put on	

The Amount of Fee.....£ 3 : — : — is received by me,

Special..... : — : —

Certificate (if required) : /O : —

Committee's Minute 10th Janry 1852

Character assigned