

REPORT of SURVEY for REPAIRS.

No. 336

on the 28

Tonnage

By whom built

Port belonging to

If Surveyed Afloat or in Dry Dock

E. J. M. & Co. 49

Survey held at

Great Britain

Built at

New Brunswick

Owners

Robinson

Destined Voyage

Callao

Date

Nov 12 1850

Master

C. Hare

When built

1846

Last Survey, No.

2696

Port

Clyde

1844 Classed

4 A expunged

REPAIRS

Wales sheathed with inch fir over paper and caulked from the Copper to the waterways

The foremast being slightly damaged in the way of the wedges of the lower deck has had five oak fishes from the lower part to four feet above the upper deck and well hooped with Iron

Present Condition of the

Decks

Waterways

Comings

Upper Deck Beams & Fastenings

Lower Deck Beams & Fastenings

Planksheers

Sheerstrakes

Topsides

Wales

Plank (Bottom) and Counter

Treenails

Breasthooks and Stemson

Transoms, Pointers, and Crutches

Timbers of the Frame

Keelsons

Clamps and Shelves

Ceiling

Rudder

Copper

When put on 1849

Windlass and Capstan

Pumps

Boats

Masts, Yards, &c.

Sails

Anchors No. of 4 Bowers 15m 2 Hedges

Cables

Hawsers and Warps

Standing & Running Rigging

General Observations and Opinion,

I am of opinion this vessel is in a good to continue as classed

The Amount of Fee.....£..... is received by me,

Special.....

Certificate (if required)

Committee's Minute

Character assigned

6th Decy 1852

4 A 1

1050



© 2019

Lloyd's Register Foundation

LON631-0259