

17330

REPORT of SURVEY for REPAIRS.

Change of Owners

No. 234 Survey held at London Date Feb 5 1852
on the By Janet Master F. Spencelayh
Tonnage 103 Built at Alton When built 1840
By whom built By whom built Owners T. Hopper
Port belonging to London Destined Voyage Coastwise
If Surveyed Afloat or in Dry Dock Fitchers Dock

Last Survey, No. 15622 Port London Classed A, 1
REPAIRS Yellow Metal stripped off, the bottom caulked, a pair of Iron pointers
ast.

| | | |
|---|---|---|
| Present Condition of the | | |
| Decks <u>good</u> | Treenails <u>good</u> | Windlass and Capstan <u>good</u> |
| Waterways <u>good</u> | Breasthooks and Stemson <u>good</u> | Pumps <u>good</u> |
| Comings <u>good</u> | Transoms, Pointers, and Crutches <u>good</u> | Boats <u>good</u> |
| Upper Deck Beams & Fastenings <u>good</u> | Timbers of the Frame <u>good when seen</u> | Masts, Yards, &c. <u>good</u> |
| Lower Deck Beams & Fastenings <u>good</u> | Keelsons <u>good</u> | Sails <u>well found</u> |
| Planksheers <u>good</u> | Clamps and Shelves <u>good</u> | Anchors No. of <u>3 Bower Stm & Kedge</u> |
| Sheerstrakes <u>good</u> | Ceiling <u>good</u> | Cables <u>well found</u> |
| Topsides <u>good</u> | Rudder <u>good</u> | Hawsers and Warps <u>good</u> |
| Wales <u>good</u> | Copper <u>stripped off</u> When put on <u>✓</u> | Standing & Running Rigging <u>good</u> |
| Plank (Bottom) and Counter <u>good</u> | | |

General Observations and Opinion, In good condition for the safe conveyance of dry &
perishable cargo & may continue as classed.

W. M. P. D. M.

The Amount of Fee.....£ / : : is received by me, *[Signature]*

Special..... : :

Certificate (if required) : :

Committee's Minute 20th Feb 1852
Character assigned A, 1 *[Signature]*