ANNUAL SURVEYS.

17338

No. 203 Survey held at London Date Febry 3rd & 4th 1852

on the Bk Reward Master Shadrake

Tonnage 325 Built at Petethead When built 1820

By whom built _____ Owners J Adams

Port belonging to London Destined Voyage Jamaica

If Surveyed Afloat or in Dry Dock Downs Dock

Last Survey, No. 15705 Port of London SS 48 Classed A1 Asterisk 50

The present Condition of the

Decks		Treenails good	Windlass and Capstan good
Waterways		Breasthooks and Stemson Do	Pumps Do
Comings		Transoms, Pointers, and Crutches Do	Boats Do
Upper Deck Beams & Fastenings		Timbers of the Frame good where seen	Masts, Yards, &c. Do
Lower Deck Beams & Fastenings		Keelsons Good	Sails Well found
Planksheers Good		Clamps and Shelfs Do	Anchors No. of 3 Bowes Stm & Kedge
Sheerstrakes		Ceiling Do	Cables well found
Topsides		Rudder Do	Hawsers and Warps Do
Wales		Copper When put on Febry 1852	Standing & Running Rigging good
Plank (Bottom) and Counter			

General Observations and Opinion, From damage has been shifted, hung part new false keel, caulked from the keel to the wales, and sheathed with Yellow Metal on paper, and is in a very good condition for the safe conveyance of dry & perishable cargoes to & from all parts of the world & may continue as classed

Committee Minute 24th Febry 1852

Character assigned A1 Asterisk 50

Sl Damage £3-3-0

R. & W. Wigram

Certificate (if required)

No. 123 Survey held at London Date Febry 9th & 13th 1852

on the S Bengal Merchant Master Jebb

Tonnage 503 Built at Calcutta When built 1812

By whom built _____ Owners Hayside

Port belonging to London Destined Voyage Adelaide

If Surveyed Afloat or in Dry Dock Young & Sons Dock

Last Survey, No. 16038 Port of London S.S. 50 Classed A1 Asterisk 50

The present Condition of the

Decks		Treenails	Windlass and Capstan good
Waterways		Breasthooks and Stemson	Pumps Do
Comings		Transoms, Pointers, and Crutches	Boats Do
Upper Deck Beams & Fastenings		Timbers of the Frame	Masts, Yards, &c. Do
Lower Deck Beams & Fastenings		Keelsons Good	Sails Well found
Planksheers Good		Clamps and Shelfs	Anchors No. of 3 Bowes Stm & Kedge
Sheerstrakes		Ceiling	Cables Well found
Topsides		Rudder	Hawsers and Warps Do
Wales		Copper W.M. When put on 1850	Standing & Running Rigging good
Plank (Bottom) and Counter			

General Observations and Opinion, From damage has had three new plks in the dry docking in the flat of the fore body & the Metal repaired, Is in a very efficient state for the safe conveyance of dry & perishable cargoes to & from all parts of the world and may continue as classed

Committee Minute 26th Febry 1852

Character assigned A1 Asterisk 50

Sl Damage £2-2-0

R. & W. Wigram

Certificate (if required)

SEYFANG AND CO. PRINTERS, 57, FARRINGDON STREET, LONDON.

© 2019 Lloyd's Register Foundation
LOND31-0297