

REPORT of SURVEY for REPAIRS.

No. 86 Survey held at London Date 8 May 18 52
on the "M. Invincible" Master Whyte
Tonnage 289 Built at Newport When built 1847
By whom built 288 Owners Capt
Port belonging to — 47 Destined Voyage New Zealand
If Surveyed Afloat or in Dry Dock London Dock

Last Survey, No. 1032 Port Newport Classed 8 A1
REPAIRS 50

Present Condition of the

Decks <u>Good</u>	Treenails <u>Good</u>	Windlass and Capstan <u>efficient</u>
Waterways <u>do</u>	Breasthooks and Stemson <u>do</u>	Pumps <u>do</u>
Comings <u>do</u>	Transoms, Pointers, and Crutches <u>do</u>	Boats <u>do</u>
Upper Deck Beams & Fastenings <u>Some</u>	Timbers of the Frame <u>When seen do</u>	Masts, Yards, &c. <u>do</u>
Lower Deck Beams & Fastenings <u>do</u>	Keelsons <u>do</u>	Sails <u>do</u>
Planksheers <u>Good</u>	Clamps and Shelves <u>do</u>	Anchors No. of <u>3. 1. 1</u> <u>do</u>
Sheerstrakes <u>do</u>	Ceiling <u>do</u>	Cables <u>do</u>
Topsides <u>do</u>	Rudder <u>do</u>	Hawsers and Warps <u>do</u>
Wales <u>do</u>	Copper <u>Amalg</u> When put on <u>1850</u>	Standing & Running Rigging <u>do</u>
Plank (Bottom) and Counter <u>A</u>		

General Observations and Opinion,

*She is in good and efficient condition and
eligible to unarm as ordered*

The Amount of Fee.....£ 1 : : is received by me,

Special..... : :

Certificate (if required) : 10 : —

Committee's Minute 11 May 1852

Character assigned S A 1



© 2019

Lloyd's Register
Foundation

LON631-0463