

# REPORT of SURVEY for REPAIRS.

17509

Recd 6 May

No. 159 Survey held at London Date March 8. 17 18 52  
 on the Mr Penningham Master G Copeland  
 Tonnage 237 Built at Belfast When built 1833  
 By whom built — Owners J Dunn  
 Port belonging to Belfast Destined Voyage —  
 If Surveyed Afloat or in Dry Dock London Dock &

Last Survey, No. 10495 Port Lpool Classed FF 1 SS 40

REPAIRS

At the present time at my suggestion

3 additional upper deck Beams and Knee cutted  
from the Copper up, and generally overhauled

Present Condition of the

Decks	<u>Good</u>	Treenails	<u>Good</u>	Windlass and Capstan	<u>efficient</u>
Waterways	<u>do</u>	Breasthooks and Stemson	<u>do</u>	Pumps	<u>do</u>
Comings	<u>do</u>	Transoms, Pointers, and Crutches	<u>do</u>	Boats	<u>do</u>
Upper Deck Beams & Fastenings	<u>Seam</u>	Timbers of the Frame	<u>do</u>	Masts, Yards, &c.	<u>do</u>
Lower Deck Beams & Fastenings	<u>do</u>	Keelsons	<u>do</u>	Sails	<u>do</u>
Planksheers	<u>Good</u>	Clamps and Shelves	<u>do</u>	Anchors No. of <u>1. 1. 1</u>	<u>do</u>
Sheerstrakes	<u>do</u>	Ceiling	<u>do</u>	Cables	<u>do</u>
Topsides	<u>do</u>	Rudder	<u>do</u>	Hawsers and Warps	<u>do</u>
Wales	<u>do</u>	Copper <u>Metall</u> When put on <u>1849</u>		Standing & Running Rigging	<u>do</u>
Plank (Bottom) and Counter	<u>do</u>				

General Observations and Opinion,

She is in good and efficient condition  
for the conveyance of dry and perishable cargo  
to & from all parts of the world and may remain

The Amount of Fee.....£..... is received by me,

Special..... 1 : 1 : - SH

Certificate (if required) .....

Committee's Minute

18 May 1852

Character assigned

FF 1 1 Metall.

Special

FF 1

SH



© 2019

Lloyd's Register  
Foundation

LO 1631-0473