

REPORT of SURVEY for REPAIRS.

17558

No. 381 Survey held at London Date May 21st 1852
 on the Sch "Rose" Master R. Buck
 Tonnage 89 Built at Barnstaple When built 1844
 By whom built _____ Owners Jeffery
 Port belonging to Bathurst Destined Voyage Africa
 If Surveyed Afloat or in Dry Dock Dry Dock

Last Survey, No. 17032 Port London Classed B. A.
 9, 51

REPAIRS

At the present time from damage
 2 new fore lengths of main keel yoful, sheppen caulked
 from the keel up, gape made good, generally overhauled
 and sheathed with yellow metal,

Present Condition of the

Decks <u>Good</u>	Treenails <u>Good</u>	Windlass and Capstan <u>efficient</u>
Waterways <u>do</u>	Breasthooks and Stemson <u>do</u>	Pumps <u>do</u>
Comings <u>do</u>	Transoms, Pointers, and Crutches <u>do</u>	Boats <u>do</u>
Upper Deck Beams & Fastenings <u>Sound</u>	Timbers of the Frame <u>do</u>	Masts, Yards, &c. <u>do</u>
Lower Deck Beams & Fastenings <u>do</u>	Keelsons <u>do</u>	Sails <u>do</u>
Planksheers <u>Good</u>	Clamps and Shells <u>do</u>	Anchors No. of <u>21</u> <u>do</u>
Sheerstrakes <u>do</u>	Ceiling <u>do</u>	Cables <u>do</u>
Topsides <u>Sound</u> <u>do</u>	Rudder <u>do</u>	Hawsers and Warps <u>do</u>
Wales <u>Sound</u> <u>do</u>	Copper <u>met</u> When put on <u>1852</u>	Standing & Running Rigging <u>do</u>
Plank (Bottom) and Counter <u>do</u>		

General Observations and Opinion,

She is in good and efficient condition and
 eligible to remain as shipped

The Amount of Fee.....£ — : 10 : — is received by me,

Special..... 3 : 3 : —

Certificate (if required) — : — :

Committee's Minute 11 June 1852

Character assigned 12 A 1 Good upon

Special damage £3.3.0



© 2019

Lloyd's Register
 Foundation

LON 632-0008