

REPORT of SURVEY for REPAIRS.

17507

No. 242 Survey held at London Date 22^d 31st May 1851
 on the Sch^r "Oliza" Master E Lowe
 Tonnage 120 Built at Lynton When built 1838
 By whom built _____ Owners Lowe & Co
 Port belonging to Souhampton Destined Voyage _____
 If Surveyed Afloat or in Dry Dock in Fore & aft dock

Last Survey, No. 14514 Port London Classed 10 A 1
 Cont 48 - 5 1/2

REPAIRS

at present bottom stripped part new false keel
 and outer stem fitted one new under brace
 and two new buttles fitted to the under
 bottom reshaped with yellow metal on felt
 the wales, topsides, and sheerstrakes scraped
 bright and bolts & brace nails driven out for
 survey found sound & good - all the rigging
 of masts & deck to the outside
 and ceiling plank, the plank sheer water ways
 and beams the main timbers right heads
 breasthooks and transoms the floors & bulkheads
 and the frame & inner surface of the outside plank
 where sea is sound & good -

Decks	Treenails	Windlass and Capstan
Waterways	Breasthooks and Stemson	Pumps overhauled
Comings	Transoms, Pointers, and Crutches	Boats
Upper Deck Beams & Fastenings	Timbers of the Frame	Masts, Yards, &c.
Lower Deck Beams & Fastenings	Keelsons	Sails
Plank sheers	Clamps and Shelves	Anchors No. of
Sheerstrakes	Ceiling	Cables
Topsides	Rudder	Hawsers and Warps
Wales	Gopper	Standing & Running Rigging
Plank (Bottom) and Counter	When put on <u>May</u>	

1852

General Observations and Opinion,

This vessel is in efficient Condition
 and in our opinion fit for the safe conveyance
 of dry perishable cargoes to & from all parts

The Amount of Fee.....£ - : 10 : - is received by me,

Special..... 3 : 3 : -

Certificate (if required) : 5 : -

Committee's Minute 11 June 1852

Character assigned A 1

[Signature]

[Signature]

Lloyd's Register
 Foundation