

ANNUAL SURVEYS.

17793

No. ¹³ on the *Bark Derwent Water* Survey held at *London* Date *14th Sept 1852*
 Tonnage *500* Built at *Sunderland* Master *W. Rankine*
 By whom built *Richardson* Owners *Richardson*
 Port belonging to *London* Destined Voyage *Robert Town*
 If Surveyed Afloat or in Dry Dock *in Lime Kiln Dock*

Last Survey, No. *4835* Port of *Sunderland* Classed *12 A 1*
 8

The present Condition of the

Decks	Treenails	Windlass and Capstan
Waterways	Breasthooks and Stemson	Pumps
Comings	Transoms, Pointers, and Crutches	Boats
Upper Deck Beams & Fastenings	Timbers of the Frame	Masts, Yards, &c.
Lower Deck Beams & Fastenings	Keelsons	Sails
Planksheers	Clamps and Shelves	Anchors No. of
Sheerstrakes	Ceiling	Cables
Topsides	Rudder	Hawsers and Warps
Wales	Copper <i>Ym</i> When put on <i>Sept 1852</i>	Standing & Running Rigging
Plank (Bottom) and Counter		

General Observations and Opinion,

At present a new false 6-false keel fitted and garboard strake not being bolted on the lower edge 32 yellow metal bolts 10" long have been driven in it on each side and the bottom sheathed with yellow metal on top new figure head fitted
 Committee Minute *1852*
 Character assigned *12 A 1* *is in efficient Condition* Certificate (if required) *W. Rankine*

No. ⁴⁸⁶ on the *Ship Daphne Merchant* Survey held at *London* Date *15th 25th 30th Sep 1852*
 Tonnage *531* Built at *Calcutta* Master *D. D. D. D.*
 By whom built *D. D. D. D.* Owners *D. D. D. D.*
 Port belonging to *London* Destined Voyage
 If Surveyed Afloat or in Dry Dock *in Snooks Dry Dock*

Last Survey, No. *1187* Port of *London* Classed *12 A 1* *SS 49*
 57

The present Condition of the

Decks	Treenails <i>overhauler</i>	Windlass and Capstan
Waterways	Breasthooks and Stemson	Pumps
Comings	Transoms, Pointers, and Crutches	Boats
Upper Deck Beams & Fastenings	Timbers of the Frame	Masts, Yards, &c.
Lower Deck Beams & Fastenings	Keelsons	Sails
Planksheers	Clamps and Shelves	Anchors No. of
Sheerstrakes	Ceiling <i>repaired</i>	Cables
Topsides	Rudder	Hawsers and Warps
Wales	Copper <i>Ym</i> When put on <i>Sept 1852</i>	Standing & Running Rigging
Plank (Bottom) and Counter		

General Observations and Opinion,

At present bottom stripped doubling of bottom and wales & topsides Caulked bottom sheathed with yellow metal is in efficient Condition
 Committee Minute *1852*
 Character assigned *12 A 1* *is in efficient Condition* Certificate (if required) *W. Rankine*