

REPORT of SURVEY for REPAIRS.

Relaying 17845

No. 144

Survey held at

London

Date

October 29th 1852

on the

Brig Amy

Master

Tonnage

168

Built at

Pool

When built

1818

By whom built

166

Owners

Bloomfield

Port belonging to

London

Destined Voyage

If Surveyed Afloat or in Dry Dock

Afloat had been in William's Slip

pt NW. 41 ND. Q 17p 50

Last Survey, No.

11280

Port

London

Classed

expunged

REPAIRS

Present Condition of the

| | | | | | |
|-------------------------------|------|----------------------------------|------------------|----------------------------|-----------|
| Decks | Good | Treenails | Good | Windlass and Capstan | efficient |
| Waterways | — | Breasthooks and Stemson | do | Pumps | do |
| Comings | — | Transoms, Pointers, and Crutches | do | Boats | do |
| Upper Deck Beams & Fastenings | Stem | Timbers of the Frame | wholesome do | Masts, Yards, &c. | do |
| Lower Deck Beams & Fastenings | do | Keelsons | Good | Sails | do |
| Planksheers | Good | Clamps and Shelves | — | Anchors No. of 11 | do |
| Sheerstrakes | do | Ceiling | — | Cables | do |
| Topsides | do | Rudder | — | Hawsers and Warps | do |
| Wales | do | Copper 4m | When put on 1847 | Standing & Running Rigging | do |
| Plank (Bottom) and Counter | do | | | | |

General Observations and Opinion,

She is in good and efficient condition fit for the conveyance of dry and perishable Cargoes to and from all parts of the world and may be relaysed in 14d

The Amount of Fee.....£ — : 10 : — is received by me,

Special..... : :

Certificate (if required) : :

Committee's Minute

5th Nov 1852

Character assigned

1st 1st

Mr Griffiths 10th 1852



© 2019

Lloyd's Register Foundation

LON 632-0304