

REPORT of SURVEY for REPAIRS.

No. 227 Survey held at London Date July 22^d 1853
 of the "H. McClellan" Master Bright
 Tonnage 250 Built at Whitehaven When built 1826
 By whom built _____ Owners Brattle
 Port belonging to Whitehaven Destined Voyage Algar Bay
 If Surveyed Afloat or in Dry Dock Greenholm Dock

Last Survey, No. 11210

Port Lanc

Classed 7th

REPAIRS

At the present time 2 planks in ceiling, shep and under shep joined the floor bolts of the keel of the deck and hold beams round some new beams.

Has been surveyed in conformity with the Surveyors Rules & has been surveyed bright from the copper up, bolts and beams, minor suit for inspection.

The upper decks and lower masts, upper and lower deck bolts and the planks through which they pass, plank beams, cutwaters, beams, bristles, bright heads, breast works, transoms, floors, pluckers, the planking outside from the upper b.p., the ceiling the frame and inner surface of the lower side plank through which it has been seen all in good condition and the sheer and general form of the hull unaltered.

Decks	Treenails	Windlass and Capstan
Waterways	<u>Green</u>	<u>efficient</u>
Comings	Breasthooks and Stenson <u>do</u>	Pumps <u>do</u>
Upper Deck Beams & Fastenings	Transoms, Pointers, and Crutches <u>do</u>	Boats <u>do</u>
Lower Deck Beams & Fastenings	Timbers of the Frame <u>do</u>	Masts, Yards, &c. <u>do</u>
Plank sheers	Keelsons <u>do</u>	Sails <u>do</u>
Sheerstrakes	Clamps and Shells <u>do</u>	Anchors No. of <u>1-1</u>
Topsides	Ceiling <u>do</u>	Cables <u>do</u>
Wales	Rudder <u>do</u>	Hawsers and Warps <u>do</u>
Plank (Bottom) and Counter	Copper <u>metal</u> When put on <u>1851</u>	Standing & Running Rigging <u>do</u>

General Observations and Opinion,

She is in good and efficient condition for for the conveyance of dry and perishable cargo to & from all parts of the world and may be valued 7th

The Amount of Fee.....£ 11 : 0 : 0 is received by me,

Special..... 3 : 3 : 0

Certificate (if required) - : 10 : 0

Committee's Minute

Character assigned

1st March 1853

R. I. Astor

W. C. & Co. Surveyors

al B

© 2019
 Lloyd's Register
 Foundation

100033-000