

ANNUAL SURVEYS.

18077

No. 87 on the *Ship "Grey"* Survey held at *London* Date *Feb 25th Mar 7* 1853
 Tonnage *145* Built at *N Seal* Master *J Smith*
 By whom built *Haggoth* When built *1845*
 Port belonging to *Mells* Owners *Haggoth*
 If Surveyed Afloat or in Dry Dock *In New Crane Dry Dock* Destined Voyage *Milbourn*

Last Survey, No. *1495* Port of *Newcastle*

Classed *4 A 1*
55° 50' 43" Lat 50.2 - 50

The present Condition of the

Decks	Treenails	Windlass and Capstan
Waterways } <i>Good</i>	Breasthooks and Stenson } <i>Good when seen</i>	Pumps
Comings	Transoms, Pointers, and Crutches	Boats
Upper Deck Beams & Fastenings	Timbers of the Frame	Masts, Yards, &c. <i>In good order and sufficient</i>
Lower Deck Beams & Fastenings <i>Good when seen</i>	Keelsons <i>d^{1/2}</i>	Sails
Plank sheers	Clamps and Shelves <i>d^{1/2}</i>	Anchors No. of
Sheerstrakes <i>d^{1/2}</i>	Ceiling <i>d^{1/2}</i>	Cables
Topsides <i>d^{1/2}</i>	Rudder <i>d^{1/2}</i>	Hawsers and Warps
Wales <i>d^{1/2}</i>	Copper <i>on hull</i> When put on <i>new near</i>	Standing & Running Rigging <i>Stuffed and Outhauls</i>
Plank (Bottom) and Counter <i>d^{1/2}</i>		

General Observations and Opinion, *Non done. One Hold Beam which was badly broken, replaced with new; Caulked outside entirely, and the Bottom Sheathed with zinc over Paper. The appears in good condition eligible to remain Classed A 1*

Committee Minute *8 March 1853*
 Character assigned *A 1* *J A Martin*
Refractions attendam 5.1.1.0 Certificate (if required)

No. 88 on the *Ship "Maria Gray"* Survey held at *London* Date *March 24th* 1853
 Tonnage *597* Built at *Newcastle* Master *Dixon*
 By whom built *Hyde & Co* When built *1853*
 Port belonging to *London* Owners *Hyde & Co*
 If Surveyed Afloat or in Dry Dock *In Nelson Dry Dock* Destined Voyage *Bombay*

Last Survey, No. *5308* Port of *Newcastle*

Classed *9 A 1*
1 mo 53

The present Condition of the

Decks	Treenails	Windlass and Capstan
Waterways } <i>Good</i>	Breasthooks and Stenson } <i>Good when seen</i>	Pumps
Comings	Transoms, Pointers, and Crutches	Boats
Upper Deck Beams & Fastenings	Timbers of the Frame	Masts, Yards, &c. <i>In good order and sufficient</i>
Lower Deck Beams & Fastenings <i>Good when seen</i>	Keelsons <i>d^{1/2}</i>	Sails
Plank sheers	Clamps and Shelves <i>d^{1/2}</i>	Anchors No. of
Sheerstrakes <i>d^{1/2}</i>	Ceiling <i>d^{1/2}</i>	Cables
Topsides <i>d^{1/2}</i>	Rudder <i>d^{1/2}</i>	Hawsers and Warps
Wales <i>d^{1/2}</i>	Copper <i>on hull</i> When put on <i>new near</i>	Standing & Running Rigging
Plank (Bottom) and Counter <i>d^{1/2}</i>		

General Observations and Opinion, *Non done. Caulked outside and the Bottom Sheathed with yellow metal over felt. She appears in good condition eligible to remain Classed A 1*

Committee Minute *8 March 1853*
 Character assigned *A 1* *J A Martin*
Refractions attendam 5.1.1.0 Certificate (if required)