

# REPORT of SURVEY for REPAIRS.

*Change of Owners*

No. *134* Survey held at *London* Date *28 Feb 74* 18*58*  
 of the *BR SOPHIA* Master  
 Tonnage *376* Built at *Chepstow* When built *1822*  
 By whom built Owners *Somers Mylloes & Co*  
 Port belonging to *London* Destined Voyage *West Indies*  
 If Surveyed Afloat or in Dry Dock *in Mr Somers's Dock*

Last Survey, No. *1700*

Port *London*

Classed *1st*

S.S. *43*

REPAIRS

This Vessel was Scraped bright and subjected to Survey with the View of determining her actual Clap - her general Condition is not of such high state as to entitle her to this high Clap - two new hold beams have been fitted of Amer Elm the bolts have been renewed in two pairs of hold beams one broken staple iron repaired & refitted - the Carling in the hold secured and repaired - outside Stanks Caulked from the yellow metal to the

Present Condition of the

Decks *Doubly good*  
 Waterways  
 Comings  
 Upper Deck Beams & Fastenings  
 Lower Deck Beams & Fastenings  
 Planksheers } *Caulked*  
 Sheerstrakes } *sufficient*  
 Topsides } *for Claps*  
 Wales } *to be renewed*  
 Plank (Bottom) and Counter

Treenails  
 Breasthooks and Stenson  
 Transoms, Pointers, and Crutches  
 Timbers of the Frame  
 Keelons  
 Clamps and Shells  
 Ceiling  
 Rudder  
 Copper *up* When put on *1848*

Windlass and Capstan  
 Pumps  
 Boats  
 Masts, Yards, &c.  
 Sails  
 Anchors No. of *3*  
 Cables  
 Hawsers and Warps  
 Standing & Running Rigging

General Observations and Opinion,

This Vessel is in efficient Condition fit for the Safe Conveyance of dry and perishable Cargoes but not for the destruction

The Amount of Fee.....£ 2 : : is received by me, of the Master  
 Special..... 1 : 1 : *2/4/53* May be Claps *A 1*

Certificate (if required)

Committee's Minute *8 Church* 18*53*

Character assigned *1st* *Wilton's Register*  
*Special 1.1* *Wilton's Register*  
*Wilton's Register*  
*Wilton's Register*