

REPORT of SURVEY for REPAIRS.

18099

George of London
 No. *✓* Survey held at *London* Date *April 19* 18*52*
 on the *S* *William* Master *Joseph G. L. Milton*
 Tonnage *191* Built at *Sunderland* When built *1852*
 By whom built *Wade & Co* Owners
 Port belonging to *London* Destined Voyage *Australia C. D. Hope*
 If Surveyed Afloat or in Dry Dock *West India Dock*
C. E.

Last Survey, No. *4642 & 17438* Port *Sunderland* Classed *13 A1*

REPAIRS

x Re-coppered at Bombay 1853
 Bulls produced Jan. 16th 1854
J. Adams

Present Condition of the

Decks	Treenails	Windlass and Capstan
Waterways	Breasthooks and Stemon	Pumps
Comings	Transoms, Pointers, and Crutches	Boats
Upper Deck Beams & Fastenings	Timbers of the Frame	Masts, Yards, &c.
Lower Deck Beams & Fastenings	Keelsons	Sails
Planksheers	Clamps and Shelves	Anchors No. of
Sheerstrakes	Ceiling	Cables
Topsides	Rudder	Hausers and Warps
Wales	Copper <i>111</i> X When put on <i>1852</i>	Standing & Running Rigging
Plank (Bottom) and Counter		

General Observations and Opinion, *Is in an efficient state to continue as classed*

The Amount of Fee.....£ *3* is received by me. *16/3/53*

Special.....

Certificate (if required)

Committee's Minute *18th March 1853*

Character assigned *13 A1*
[Signature]

© 2019 Lloyd's Register Foundation

LOW633-0039