

REPORT of SURVEY for REPAIRS.

18187

No. 172. Survey held at London Date April 13 1885
 on the Ship Gilmour Master John Mac Scott
 Tonnage 500 Built at Barcelona When built 1824
 By whom built — Owners Jarguhansen
 Port belonging to London Destined Voyage for date
 If Surveyed Afloat or in Dry Dock Afloat W.I.D.D.

Last Survey, No. 17189 Port London Classified 11 A 1
SS 42
 REPAIRS

Present Condition of the

Decks <u>good</u>	Treenails <u>—</u>	Windlass and Copstan <u>efficient</u>
Waterways <u>do</u>	Breasthooks and Stenson <u>good</u>	Pumps <u>do</u>
Comings <u>do</u>	Transoms, Pointers, and Crytches <u>do</u>	Boats <u>do</u>
Upper Deck Beams & Fastenings <u>do</u>	Timbers of the Frame <u>wholesome</u>	Masts, Yards, &c. <u>do</u>
Lower Deck Beams & Fastenings <u>do</u>	Keelsons <u>do</u>	Sails <u>do</u>
Planksheers <u>good</u>	Clamps and Shells <u>do</u>	Anchors No. of <u>3 1 1</u> <u>do</u>
Sleeerstrakes <u>do</u>	Ceiling <u>do</u>	Cables <u>do</u>
Topsides <u>do</u>	Rudder <u>do</u>	Hawsers and Warps <u>do</u>
Wales <u>do</u>	Copper <u>white</u> When put on <u>1865</u>	Standing & Running Rigging <u>do</u>
Plank (Bottom) and Counter <u>—</u>		

General Observations and Opinion,

She is in good and efficient condition for the conveyance of dry and perishable cargoes to & from all ports of the world and may remain so long.

The Amount of Fee.....£ 3 : : is received by me,

Special..... : : W. H. 1885

Certificate (if required) : do :

Committee's Minute W. H. 1885

Character assigned First Class

Lloyd's Register
 Foundation

LON 633-0124