

18259

REPORT of SURVEY for REPAIRS.

No. 1523 Survey held at London Date 6.10.13.18 Mar 1853
 on the Ship "Mile" Master E P Mitchell
 Tonnage 1100 Built at London When built 1850
 By whom built _____ Owners R Crey
 Port belonging to London Destined Voyage India
 If Surveyed Afloat or in Dry Dock in Messrs Green's Dock

Last Survey, No. 17480 Port London Classed 12 A 1

REPAIRS at present from having been out of 53 hours during her late voyage from Calcutta entirely new Main-Middle & Fore Keels fitted - bottom stripped - 17 Planks of the bottom removed on the Starboard and 5 on the larboard side being nearly chafed & badly worn - 5 new Planks of bilge curving on the Starboard side which have been additionally thro' bottom - Caulked from keel to waterways and bottom kedged with dark yellow putty - Fall damage repaired

Decks	Treenails	Windlass and Capstan
Waterways	Breasthooks and Stenson	Pumps
Comings	Transoms, Pointers, and Crutches	Boats
Upper Deck Beams & Fastenings	Timbers of the Frame	Masts, Yards, &c.
Lower Deck Beams & Fastenings	Keelsons	Sails
Planksheers	Clamps and Shelves	Anchors No. of
Sheerstrakes	Ceiling	Cables
Top-sides	Rudder	Haulsers and Warps
Wales	Copper	Standing & Running Rigging
Plank (Bottom) and Counter		

Present Condition of the Good Good our new successful

General Observations and Opinion, This vessel is again in most efficient condition and fit to be repaired as ordered

The Amount of Fee.....£ 3 : : is received by me. E P Mitchell
 Special..... 4 : 4 : J H

Certificate (if required) _____
 Committee's Minute 14th June 1853
 Character assigned 12 A 1 Green's Dock
 Special £ 4. 4. J H