

18279
53



Turkey

3, 53

Decks
Waterways
Comings
Upper Deck Beams & Fastenings
Lower Deck Beams & Fastenings
Planksheers
Sheerstrakes
Topside
Wales
Plank (Bottom) and Counter

Treenails _____
Breasthooks and Stemson _____
Transoms, Pointers, and Crutches _____
Timbers of the Frame _____
Keelsons _____
Clamps and Shelves _____
Ceiling _____
Rudder *Upstayed*
Copper *Hand* When put _____

Windlass and Capstan _____

Pumps _____

Boats _____

Masts, Yards, &c. _____

Sails _____

Anchors No. of _____

Cables _____

Hawsers and Warps _____

Standing & Running Rigging _____

at present bottom blacks additionally
 taken from Kiel up and bottom sheeted
 17 June 1803 is in efficient condition
 and fit to begin as before
 D. Brown, St. Kitts
 Certificate (if required)

Certificate (if required)

Rey.

London

5, 52

Decks _____
Waterways _____
Comings _____
Upper Deck Beams & Fastenings _____
Lower Deck Beams & Fastenings _____
Planksheers _____
Sheerstrakes _____
Topsidess *Caulked*
Wales _____
Plank (Bottom) and Counter _____

Treenails _____
Breasthooks and Stemson _____
Transoms, Pointers, and Crutches _____
Timbers of the Frame _____
Keelsons _____
Clamps and Shelves _____
Ceiling _____
Rudder _____
Copper _____ When put

Windlass and Capstan
Pumps
Boats
Masts, Yards, &c.
Sails
Anchors No. of
Cables
Hawsers and Warps
Standing & Running Rigging

at present give additionally bottles
total (3 bottles) thus for each of father's feet
Yellow Nitrate & Sarsil is in excellent
condition for the feet to be kept in
as Charles C. Hatcher

Certificate (if required)