ANNUAL SURVEYS.

18279

Supp. 22

No. _____ Survey held at London Date 30 April & June 1853

on the Ship Clara Master _____

Tonnage 614 704 Built at Sunderland When built 1853

By whom built _____ Owners J. Sudcombe

Port belonging to London Destined Voyage _____

If Surveyed Afloat or in Dry Dock in Messrs Young's Dock

Last Survey, No. 4968 Port of Sunderland Classed 10 A 1 3.53

The present Condition of the

Decks		Treenails		Windlass and Capstan	
Waterways	Coal Red	Breasthooks and Stemson		Pumps	
Comings		Transoms, Pointers, and Crutches		Boats	
Upper Deck Beams & Fastenings		Timbers of the Frame		Masts, Yards, &c.	Good
Lower Deck Beams & Fastenings		Keelsons	Good	Sails	
Planksheers		Clamps and Shelfs		Anchors No. of	&
Sheerstrakes		Ceiling		Cables	Sufficient
Topsides		Rudder Unfastened		Hawsers and Warps	
Wales		Copper Yes When put on May 1853		Standing & Running Rigging	
Plank (Bottom) and Counter					

General Observations and Opinion,

at present bottom planks additionally bolted Coal Red from Keel up and bottom sheathed with Yellow Metal is in efficient Condition

Committee Minute 21 June 1853 and fit to Repeat as Clipper

Character assigned 10 A 1 Pr

J. W. Ritchie

Certificate (if required)

No. 118 Survey held at London Date 11 May 1853

on the Ship "Wellesley" Master Parish

Tonnage 1014 1102 Built at London When built 1847

By whom built _____ Owners R. Green

Port belonging to London Destined Voyage Calcutta

If Surveyed Afloat or in Dry Dock in Messrs Green's Lower Dock

---

Last Survey, No 17334 Port of London Classed 12 A 1 5.52

The present Condition of the

Decks		Treenails		Windlass and Capstan	
Waterways	Good	Breasthooks and Stemson		Pumps	
Comings		Transoms, Pointers, and Crutches		Boats	
Upper Deck Beams & Fastenings		Timbers of the Frame		Masts, Yards, &c.	Good
Lower Deck Beams & Fastenings		Keelsons	Good	Sails	
Planksheers		Clamps and Shelfs		Anchors No. of	&
Sheerstrakes		Ceiling		Cables	Sufficient
Topsides Coal Red		Rudder		Hawsers and Warps	
Wales		Copper Yes When put on 1852		Standing & Running Rigging	
Plank (Bottom) and Counter					

General Observations and Opinion,

at present yards additionally bolted with 1st Yellow Metal (3 bolts) Mess from Deck fitted and Yellow Metal Sheathed is in efficient

Committee Minute 21 June 1853 Condition fit to Repeat as Clipper

Character assigned 12 A 1 Pr

J. W. Ritchie

Certificate (if required)

SKYFANG AND CO. PRINTERS, 57, FARRINGDON STREET, LONDON.

© 2019 Lloyd's Register Foundation

LON633-0217