

ANNUAL SURVEYS.

1853

No. 30 Survey held at London Date 8th July 18 53
 on the Ship Saladin Master Masterston
 Tonnage 736 Built at Sunderland When built 1837
 By whom built Henderson Owners Henderson
 Port belonging to London Destined Voyage St Philip
 If Surveyed Afloat or in Dry Dock Prince's Dry Dock

[Handwritten signature]

Last Survey, No. 17559 Port of London Classed B D

The present Condition of the

Decks <u>Good</u>	Treenails	Windlass and Capstan
Waterways <u>B</u>	Breasthooks and Stenson	Pumps
Comings <u>B</u>	Transoms, Pointers, and Crutches	Boats
Upper Deck Beams & Fastenings <u>Fair</u>	Timbers of the Frame	Masts, Yards, &c. <u>Good & Saff</u>
Lower Deck Beams & Fastenings <u>B</u>	Keelsons	Sails
Planksheers	Clamps and Shelves	Anchors No. of
Sheerstrakes	Ceiling	Cables
Topsides	Rudder	Hawsers and Warps
Wales	Copper <u>Yellow</u> When put on <u>July 1853</u>	Standing & Running Rigging
Plank (Bottom) and Counter		

General Observations and Opinion, At present, bottom stripped to find a leak, and yellow metal caulked, two holes open one on Port bow the other in the water of main channel. She is in efficient condition and we think her eligible to remain as classed.
 Committee's Minute 10th July 1853

Character assigned 13 D 1st group Charles C. R. R. Certificate (if required)

No. 302 Survey held at London Date July 11th 18 53
 on the Bark Chapman's Master H. Charles
 Tonnage 281 Built at Whitby When built 1845
 By whom built Wm Chapman Owners Philpot &
 Port belonging to London Destined Voyage
 If Surveyed Afloat or in Dry Dock Gun Dry Dock

Last Survey, No. 17702 Port of London Classed 10 D

The present Condition of the

Decks <u>Good</u>	Treenails	Windlass and Capstan
Waterways <u>B</u>	Breasthooks and Stenson	Pumps
Comings <u>B</u>	Transoms, Pointers, and Crutches	Boats
Upper Deck Beams & Fastenings <u>Fair</u>	Timbers of the Frame	Masts, Yards, &c. <u>Good & Saff</u>
Lower Deck Beams & Fastenings	Keelsons	Sails
Planksheers	Clamps and Shelves	Anchors No. of
Sheerstrakes	Ceiling	Cables
Topsides	Rudder	Hawsers and Warps
Wales	Copper <u>Yellow</u> When put on	Standing & Running Rigging
Plank (Bottom) and Counter		

General Observations and Opinion, At present, bottom stripped, sheathed with yellow metal over felt & caulked. She is in efficient condition and we think her eligible to remain as classed.
 Committee's Minute 10th July 1853

Character assigned 10 D 1st group Charles C. R. R. Certificate (if required)