

# ANNUAL SURVEYS.

18379

No. 162 Survey held at London Date 9<sup>th</sup> July 1853  
 on the Barck Ancharter Master M. Duttie  
 Tonnage 428 Built at Aberdeen When built 1851  
 By whom built Duttie Owners Duttie  
 Port belonging to Aberdeen Destined Voyage Australia  
 If Surveyed Afloat or in Dry Dock Dowson dry Dock

Dec 25 1853

Last Survey, No.	Port of <u>Duplicate</u>	Classed <u>G. A. 1</u>
The present Condition of the		
Decks <u>Good</u>	Treenails	Windlass and Capstan <u>Good</u>
Waterways <u>do</u>	Breasthooks and Stenson	Pumps <u>do</u>
Comings <u>do</u>	Transoms, Pointers, and Crutches	Boats <u>do</u>
Upper Deck Beams & Fastenings	Timbers of the Frame	Masts, Yards, &c.
Lower Deck Beams & Fastenings	Keelsons <u>Good</u>	Sails
Planksheers <u>Good</u>	Clamps and Shelves <u>Good</u>	Anchors No. of
Sheerstrakes <u>Good</u>	Ceiling	Cables <u>Good</u>
Topsides	Rudder	Hawsers and Warps
Wales	Copper <u>White</u> When put on <u>new</u>	Standing & Running Rigging
Plank (Bottom) and Counter		
General Observations and Opinion. <u>The yellow metal has been stripped off its present and caulked from keel to wales and fastened with yellow metal over paper on the bottom and four courses of planks under the upper course of yellow metal. She appears in good condition at present fit to remain</u>		
Committee's Minute <u>18</u>		
Character assigned <u>do</u>		M. M. Intyre
Certificate (if required)		

No. 162 Survey held at London Date 12 July 1853  
 on the Barck Ancharter Master Clark  
 Tonnage 428 Built at S. P. Lewis When built 1840  
 By whom built do Owners do  
 Port belonging to London Destined Voyage uncertain  
 If Surveyed Afloat or in Dry Dock in N. India Dredge and in some place

Last Survey, No. <u>16993</u>	Port of <u>London</u>	Classed <u>G. A. 1</u>
The present Condition of the		
Decks	Treenails	Windlass and Capstan <u>Good</u>
Waterways	Breasthooks and Stenson	Pumps <u>do</u>
Comings	Transoms, Pointers, and Crutches	Boats <u>do</u>
Upper Deck Beams & Fastenings	Timbers of the Frame	Masts, Yards, &c. <u>do</u>
Lower Deck Beams & Fastenings	Keelsons <u>Good</u>	Sails <u>two</u>
Planksheers <u>Good</u>	Clamps and Shelves <u>Good</u>	Anchors No. of <u>do</u>
Sheerstrakes	Ceiling	Cables <u>Good</u>
Topsides	Rudder	Hawsers and Warps
Wales	Copper <u>White</u> When put on <u>1850</u>	Standing & Running Rigging
Plank (Bottom) and Counter		
General Observations and Opinion. <u>She has been in dry Dock at the present time the bottom has been examined and the yellow metal patched. She appears to be in good condition and fit to remain as classed</u>		
Committee's Minute <u>21<sup>st</sup> July 1853</u>		
Character assigned <u>C.P. 3A</u>		M. M. Intyre
Certificate (if required)		

1853-54