

ANNUAL SURVEYS.

10396
10396

No. 10 Survey held at London Date 16 July 18 53
 on the Ship Bernice Master Bonette
 Tonnage 632 Built at London When built 1834
 By whom built _____ Owners H Green
 Port belonging to London Destined Voyage East India
 If Surveyed Afloat or in Dry Dock Green dry Dock

Last Survey, No. 17307 Port of London Classed 12 A
Class 12 A
Cond 12 A for 8 yr

The present Condition of the	Treenails	Windlass and Capstan
Decks	Breasthooks and Stenson	Pumps
Waterways	Transoms, Pointers, and Crutches	Boats
Comings	Timbers of the Frame	Masts, Yards, &c.
Upper Deck Beams & Fastenings	Keelsons <u>Wooden</u>	Sails <u>Good Kaffians</u>
Lower Deck Beams & Fastenings <u>Wooden</u>	Clamps and Shelves	Anchors No. of
Planksheers	Ceiling	Cables
Sheerstrakes	Rudder	Hausers and Warps
Topsides	Copper <u>Plated</u> When put on <u>1853</u>	Standing & Running Rigging <u>Good</u>
Wales		
Plank (Bottom) and Counter		

General Observations and Opinion, This vessel has had 577 Treennails renewed in the rigging and bottom and four Struts of Fore Woods of these renewed on the Port and Starboard Sides with English Oak the Yellow Metal stripped off and the vessel hung in Shrove and covered from the upward and resheathed with Yellow Metal over the side in good condition fit to remain as classed

Committee's Minute 19th July 1853
 Character assigned Rest S A 1 revised Ym MWA
 Certificate (if required) _____

No. 60 Survey held at London Date 16 July 18 53
 on the Ship Bernice Master Viper
 Tonnage 976 Built at London When built 1829
 By whom built _____ Owners H Green
 Port belonging to London Destined Voyage East India
 If Surveyed Afloat or in Dry Dock Green dry Dock

Last Survey, No. 11636 Port of London Classed 12 A
Class 12 A
Cond 57 for 4 yr

The present Condition of the	Treenails	Windlass and Capstan
Decks	Breasthooks and Stenson	Pumps
Waterways	Transoms, Pointers, and Crutches	Boats
Comings	Timbers of the Frame	Masts, Yards, &c.
Upper Deck Beams & Fastenings	Keelsons <u>Wooden</u>	Sails <u>Good Kaffians</u>
Lower Deck Beams & Fastenings	Clamps and Shelves	Anchors No. of
Planksheers <u>Wooden</u>	Ceiling	Cables
Sheerstrakes	Rudder	Hausers and Warps
Topsides	Copper <u>Plated</u> When put on <u>57</u>	Standing & Running Rigging <u>Good</u>
Wales		
Plank (Bottom) and Counter		

General Observations and Opinion, At the present time the fore part of fore keel new and yellow metal patches she appears to be in good condition and fit to remain as classed

Committee's Minute 29th July 1853
 Character assigned Rest H P 1 MWA
 Certificate (if required) _____

LON 633-0329