

18420

REPORT of SURVEY for REPAIRS.

No. ✓ Survey held at London Date 5th 10th mo 1855
 on the Barb. Clewson Master D. Thomas
 Tonnage 450 Built at London When built 1824
 By whom built _____ Owners Wm. F. C.
 Port belonging to London Destined Voyage Honduras
 If Surveyed Afloat or in Dry Dock At the Main Mast Afloat
N.D. T. S. & S. P. S. & Co.

L
See 1200

Survey, No. 1038 Port London Classed 10th R. S. Shipmaster
 SS 48 SD

At the present time boxes of Ceiling removed with English
 and new main and Mizzen Masts
 The Owner has procured bolts and a certificate from the
 surveyors of Customs certifying that she had been shipped
 with new main Mast and Re-shoehorned with Galvan
 metal over part Sails and paper, on the 13th July 1852

for early
for repairs, page 48

Condition of the	<u>Good</u>	Treenails	Windlass and Copstan
Decks	<u>Do</u>	Breasthooks and Stenson	Pumps
Beams	<u>Do</u>	Transoms, Pointers, and Crutches	Boats
Deck Beams & Fastenings	}	Timbers of the Frame	Masts, Yards, &c.
Deck Beams & Fastening		Keelsons	Sails
Sheers	}	Clamps and Shelves	Anchors No. of
Trunks		Ceiling	Cables
Decks	}	Rudder	Hawsers and Warps
(Bottom) and Counter		Copper of Plates When put on <u>July 1852</u>	Standing & Running Rigging

General Observations and Opinion, This vessel appears to be in good condition at present and fit for the safe conveyance of any and perishable goods to and from all parts of the World and in opinion eligible to reclassify.

Amount of Fee..... £ 1 : - : - is received by me, M. W. Intype
 Special..... 1 : 1 : -

Certificate (if required) : 10 : -
 Committee's Minute 10 Aug 1855
 Character assigned Fit to receive cargo
J. Ellery

© 2019 Lloyd's Register Foundation