

# ANNUAL SURVEYS.

1853

No. 36 Survey held at London Date 20th May 1853  
 on the Barck "Notemessa" Master Bartholomew J. Bampf  
 Tonnage 492 Built at Sunderland When built 1847  
 By whom built — Owners A. Ridley  
 Port belonging to London Destined Voyage Australian  
 If Surveyed Afloat or in Dry Dock Dowson's Dry Dock

Last Survey, No. 17725 Port of London Classed 12 A1  
 53

The present Condition of the

Decks <u>Good</u>	Treenails	Windlass and Capstan
Waterways <u>Do</u>	Breasthooks and Stenson	Pumps
Comings <u>Do</u>	Transoms, Pointers, and Crutches	Boats
Upper Deck Beams & Fastenings <u>Good</u>	Timbers of the Frame	Masts, Yards, &c. <u>Good</u>
Lower Deck Beams & Fastenings <u>Good</u>	Keelsons <u>Good</u>	Sails
Planksheers <u>Do</u>	Clamps and Shelves	Anchors No. of <u>34 1/2</u>
Sheerstrakes <u>Do</u>	Ceiling	Cables <u>Safe</u>
Topsides <u>Do</u>	Rudder	Hawsers and Warps
Wales <u>Do</u>	Copper	Standing & Running Rigging
Plank (Bottom) and Counter <u>Do</u>	When put on <u>1852</u>	

General Observations and Opinion, The following repairs have been done in Butcher's Mine after  
Hoops of outside Planking new of East India Sea. Two timbers near the  
London Sinker and a Through Cheek of English Oak on the starboard  
Side. Seven after Hoops of Planking on starboard side new of East India  
Side. New Horns three of English Oak. New lower Masts and Rigging.  
Refitted. New gear and spars built. She is now in good condition  
Committee's Minute 18 Oct 1853

Character assigned

See L. 1. 1. - 12 A1

Serial 51-1-0

M. M. Latimer  
 J. C. Martin  
 Certificate (if required)

No. 48 Survey held at London Date 11th Oct 1853  
 on the Barck "Lady Katherine Barkham" Master Calverley  
 Tonnage 321 Built at London When built 1834  
 By whom built — Owners Hantley  
 Port belonging to London Destined Voyage West India  
 If Surveyed Afloat or in Dry Dock Dowson's Dry Dock

Last Survey, No. 17778 Port of London Classed 12 A1  
 53

The present Condition of the

Decks <u>Good</u>	Treenails	Windlass and Capstan
Waterways <u>Do</u>	Breasthooks and Stenson	Pumps
Comings <u>Do</u>	Transoms, Pointers, and Crutches	Boats
Upper Deck Beams & Fastenings <u>Good</u>	Timbers of the Frame	Masts, Yards, &c. <u>Good</u>
Lower Deck Beams & Fastenings <u>Good</u>	Keelsons <u>Good</u>	Sails
Planksheers <u>Do</u>	Clamps and Shelves	Anchors No. of <u>34 1/2</u>
Sheerstrakes <u>Do</u>	Ceiling	Cables <u>Good</u>
Topsides <u>Do</u>	Rudder	Hawsers and Warps
Wales <u>Good and Decayed</u>	Copper	Standing & Running Rigging
Plank (Bottom) and Counter <u>Good</u>	When put on	

General Observations and Opinion, The yellow paint stripped off the bottom and  
and Caulked from keel upwards sheathed with yellow paint  
over felt two new planks on Wales on starboard side renewed with  
English Oak two short planks on Butcher's and Wales renewed where  
defective she is in good condition at present and fit for service  
Committee's Minute 18 Oct 1853

Character assigned

See L. 1. 1. - 12 A1

Serial 51-1-0

M. M. Latimer  
 Charles Goddard  
 Certificate (if required)

201633-0107