

ANNUAL SURVEYS.

18623

No. ³²¹ on the *Bark Grecian* Survey held at *London* Date *21st Oct^r* 1853
 Master *Ally Hutchison*
 Tonnage *334* Built at *Sunderland* When built *1849*
 By whom built _____ Owners *James Thomson & Co*
 Port belonging to *London* Destined Voyage *Jamaica*
 If Surveyed Afloat or in Dry Dock *in Bilbes Dock*

Last Survey, No. *15973* Port of *London* Classed *8 A 1*
 30

The present Condition of the

Decks	Treenails	Windlass and Capstan
Waterways	Breasthooks and Stemson	Pumps
Comings	Transoms, Pointers, and Crutches	Boats
Upper Deck Beams & Fastenings	Timbers of the Frame	Masts, Yards, &c. <i>3 masts 10 yards 100 fms</i>
Lower Deck Beams & Fastenings	Keelsons	Sails
Planksheers	Clamps and Shelves	Anchors No. of <i>3</i>
Sheerstrakes	Ceiling	Cables
Topsides	Rudder	Hawsers and Warps
Wales	Copper <i>Ym</i> When put on <i>Oct 53</i>	Standing & Running Rigging
Plank (Bottom) and Counter		

General Observations and Opinion,

at present bottom stripped hung in shaws and Caulked and sheathed with yellow metal on felt above paper below - It is efficient
 Committee's Minute *22nd Nov^r 1853* Condition and fit *again*
 Character assigned *8 A 1* of class *Hutchison*
 Certificate (if required)

No. ⁴⁹ on the *Ship "Indiana"* Survey held at *London* Date *17th Oct^r* 1853
 Master _____
 Tonnage *542* Built at *Montrose* When built *1852*
 By whom built _____ Owners *J. D. Birnie*
 Port belonging to *Montrose* Destined Voyage _____
 If Surveyed Afloat or in Dry Dock *in Princes Dock*

Last Survey, No. *17741* Port of *London* Classed *12 A 1*
 32

The present Condition of the

Decks	Treenails	Windlass and Capstan
Waterways	Breasthooks and Stemson	Pumps
Comings	Transoms, Pointers, and Crutches	Boats
Upper Deck Beams & Fastenings	Timbers of the Frame	Masts, Yards, &c. <i>Good</i>
Lower Deck Beams & Fastenings	Keelsons	Sails
Planksheers	Clamps and Shelves	Anchors No. of <i>Sufficient</i>
Sheerstrakes	Ceiling	Cables
Topsides	Rudder	Hawsers and Warps
Wales	Copper <i>Ym</i> When put on <i>1852</i>	Standing & Running Rigging
Plank (Bottom) and Counter		

General Observations and Opinion,

at present docked to inspect the state of the yellow metal sheathing which has been repaired. She appears in efficient condition
 Committee's Minute *22nd Nov^r 1853* Condition and fit *again*
 Character assigned *12 A 1* of class *Hutchison*
 Certificate (if required)

104634-0041