

ANNUAL SURVEYS.

18736

No. 496 Survey held at London Date 21st & 24th June 1854
 on the Barge Speed Master Jackson
 Tonnage 262 Built at Isle of Mann When built 1842
 By whom built _____ Owners Wheelwright
 Port belonging to Whithaven Destined Voyage Swansea &
 If Surveyed Afloat or in Dry Dock Lime Kiln Ship

Last Survey, No. 1261 Port of Whithaven

Classed 1st & 2nd Class
1852

The present Condition of the

Decks	Treenails	Windlass and Capstan
Waterways	Breasthooks and Stemson	Pumps
Comings	Transoms, Pointers, and Crutches	Boats
Upper Deck Beams & Fastenings	Timbers of the Frame	Masts, Yards, &c.
Lower Deck Beams & Fastenings	Keelsons	Sails
Planksheers	Clamps and Shelves	Anchors No. of
Sheerstrakes	Ceiling	Cables
Topsides	Rudder	Hawsers and Warps
Wales	Copper	Standing & Running Rigging
Plank (Bottom) and Counter		

General Observations and Opinion, At the present time the Main Keel on the under
part where a shot of yellow Metal had been rubbed and partially
formed which has been cut into and found not to extend in
more than two inches which has been made good by piecing
two new stanchions on the port Bow, the yellow Metal patched
and waterway repaired. Condition and fit to remain as classed
Committee's Minute 27th Jan 1854
 Character assigned 1st Class M. M. Intype

Certificate (if required)

No. 288 Survey held at London Date 16th June 1854
 on the Barge Point Master Burgess
 Tonnage 311 Built at London When built London 1848
 By whom built _____ Owners Thomson
 Port belonging to London Destined Voyage Jamaica
 If Surveyed Afloat or in Dry Dock Fletcher's dry Dock

Last Survey, No. 17223 Port of London

Classed 13th A1
52

The present Condition of the

Decks	Treenails	Windlass and Capstan
Waterways	Breasthooks and Stemson	Pumps
Comings	Transoms, Pointers, and Crutches	Boats
Upper Deck Beams & Fastenings	Timbers of the Frame	Masts, Yards, &c.
Lower Deck Beams & Fastenings	Keelsons	Sails
Planksheers	Clamps and Shelves	Anchors No. of
Sheerstrakes	Ceiling	Cables
Topsides	Rudder	Hawsers and Warps
Wales	Copper	Standing & Running Rigging
Plank (Bottom) and Counter		

General Observations and Opinion, At the present time yellow Metal patched on
on the Bottom and the Keel of head repaired
she appears to be in good Condition and fit to remain
as classed

Committee's Minute 27th Jan 1854

Character assigned 13th A1 M. M. Intype

Certificate (if required)

101634-0156