

ANNUAL SURVEYS.

18860

No. 265 on the Brig "Promo" Survey held at London Date Feb 7th & 8th 1854
 Master Derecourt
 Tonnage 178 Built at Berwick When built 1842
 By whom built Swanzy Owners Swanzy
 Port belonging to London Destined Voyage Coast of Africa
 If Surveyed Afloat or in Dry Dock Fletcher's dry Dock

Recd 17 March

Last Survey, No. 17890 Port of London Classed 10 A 1
Cont 52 for 3 yrs

The present Condition of the

Decks <u>Good as new</u>	Treenails	Windlass and Capstan
Waterways <u>Do</u>	Breasthooks and Stemson	Pumps
Comings <u>Do</u>	Transoms, Pointers, and Crutches	Boats
Upper Deck Beams & Fastenings <u>Good</u>	Timbers of the Frame	Masts, Yards, &c.
Lower Deck Beams & Fastenings <u>Shaken</u>	Keelsons <u>Good as new</u>	Sails <u>Good and</u>
Planksheers	Clamps and Shelves <u>Seen</u>	Anchors No. of <u>38</u> <u>Suffice</u>
Sheerstrakes	Ceiling	Cables
Topsides	Rudder	Hawsers and Warps
Wales	Copper <u>Y Metal</u> When put on <u>New</u>	Standing & Running Rigging
Plank (Bottom) and Counter		

General Observations and Opinion,

Yellow Metal Sheathing stripped off the Bottom and Caulked from Keel upwards and the bottom resheathed with Y metal over tarpaper. She appears to be in good Condition fit to remain as classed.

Committee's Minute 21st March 1854

Character assigned 10 A 1 Good Richard Bethell
Special £1.1.0 Certificate (if required)

No. 118 on the Brig "West" Survey held at London Date 4th March 1854
 Master Thomton & West
 Tonnage 409 Built at Sunderland When built 1848
 By whom built London Owners Thomton & West
 Port belonging to London Destined Voyage Datavia
 If Surveyed Afloat or in Dry Dock Fletcher's dry Dock

Last Survey, No. 16857 Port of London Classed 13 A 1
57

The present Condition of the

Decks	Treenails	Windlass and Capstan
Waterways	Breasthooks and Stemson	Pumps
Comings	Transoms, Pointers, and Crutches	Boats
Upper Deck Beams & Fastenings	Timbers of the Frame <u>Good</u>	Masts, Yards, &c. <u>Good</u>
Lower Deck Beams & Fastenings <u>Good</u>	Keelsons <u>Shaken</u>	Sails <u>Suff</u>
Planksheers <u>Shaken</u>	Clamps and Shelves	Anchors No. of <u>38</u>
Sheerstrakes	Ceiling	Cables
Topsides	Rudder	Hawsers and Warps
Wales	Copper <u>Y Metal</u> When put on <u>New</u>	Standing & Running Rigging
Plank (Bottom) and Counter		

General Observations and Opinion,

At the present time the Bottom Caulked & sheathed with Yellow Metal over felt. She appears to be in good Condition and fit to remain as classed.

Committee's Minute 21st March 1854

Character assigned 13 A 1 Good Richard Bethell
Special £1.1.0 Certificate (if required)

LON 634-0280

