

ANNUAL SURVEYS.

18880

No. 272 Survey held at London Date 17th & 24th March 1854
on the Ship "Plantagenet" Master Pollock
Tonnage 687 Built at Newcastle When built 1838
By whom built _____ Owners Watson & Co
Port belonging to London Destined Voyage Sydney
If Surveyed Afloat or in Dry Dock Young's dry dock

Last Survey, No. 18065 Port of London Classed 12 A 1
Cont 50. 4 2

The present Condition of the

Decks <u>Good</u>	Treenails	Windlass and Capstan
Waterways <u>"</u>	Breasthooks and Stemson	Pumps
Comings <u>"</u>	Transoms, Pointers, and Crutches	Boats
Upper Deck Beams & Fastenings	Timbers of the Frame <u>Good where</u>	Masts, Yards, &c. <u>Good and</u>
Lower Deck Beams & Fastenings	Keelsons <u>seen</u>	Sails <u>sufficient</u>
Planksheers <u>Good where</u>	Clamps and Shelves	Anchors No. of <u>3. 1. 1</u>
Sheerstrakes <u>seen</u>	Ceiling	Cables
Topsides	Rudder	Hawsers and Warps
Wales	Copper <u>Y. Metal</u> When put on <u>1852</u>	Standing & Running Rigging
Plank (Bottom) and Counter		

General Observations and Opinion, Now done, Yellow metal patched and topsides caulked.
The upper deck beam found to be decayed, renewed with English Oak.
This vessel is in a good and efficient state of repair, and
is, in our opinion, eligible to remain as classed.

Committee's Minute 28th March 1854

Character assigned Cont 4 A 1

Richard Abethell
M M Intyre

Certificate (if required)

No. _____ Survey held at _____ Date _____ 185____
on the _____ Master _____
Tonnage _____ Built at _____ When built _____
By whom built _____ Owners _____
Port belonging to _____ Destined Voyage _____
If Surveyed Afloat or in Dry Dock _____

Last Survey, No. _____ Port of _____ Classed _____

The present Condition of the

Decks	Treenails	Windlass and Capstan
Waterways	Breasthooks and Stemson	Pumps
Comings	Transoms, Pointers, and Crutches	Boats
Upper Deck Beams & Fastenings	Timbers of the Frame	Masts, Yards, &c.
Lower Deck Beams & Fastenings	Keelsons	Sails
Planksheers	Clamps and Shelves	Anchors No. of
Sheerstrakes	Ceiling	Cables
Topsides	Rudder	Hawsers and Warps
Wales	Copper _____ When put on _____	Standing & Running Rigging
Plank (Bottom) and Counter		

General Observations and Opinion,

Committee's Minute _____ 185____

Character assigned _____



© 2019

Certificate (if required)

Lloyd's Register
Foundation

101634-0300