

ANNUAL SURVEYS.

18965

No. 109 Survey held at London Date April 25 / May 1 185 4
 on the Ship "Wellesley" Master Quirk
 Tonnage 1014 Built at London When built 1844
 By whom built _____ Owners R Green
 Port belonging to London Destined Voyage Madras & Calcutta
 If Surveyed Afloat or in Dry Dock In Miss Green's Dry Dock

Last Survey, No. 18279 Port of London Classed 12 A 1

The present Condition of the

Decks	Treenails	Windlass and Capstan
Waterways } <u>Good</u>	Breasthooks and Stemson	Pumps
Comings	Transoms, Pointers, and Crutches } <u>Good when used</u>	Boats
Upper Deck Beams & Fastenings	Timbers of the Frame	Masts, Yards, &c. } <u>In good order</u>
Lower Deck Beams & Fastenings } <u>When seen</u>	Keelsons } <u>d³</u>	Sails } <u>and sufficient</u>
Planksheers	Clamps and Shelves } <u>d³</u>	Anchors No. of
Sheerstrakes } <u>d³</u>	Ceiling } <u>d³</u>	Cables
Topsides } <u>d³</u>	Rudder } <u>d³</u>	Hawsers and Warps
Wales } <u>d³</u>	Copper } <u>Metal on</u> When put on <u>new new</u>	Standing & Running Rigging
Plank (Bottom) and Counter } <u>d³</u>	Paper	

General Observations and Opinion,

Now done. Yellow Metal Sheathing stripped off and renewed upon Paper. Ship hung in Shores, Bottom, Wales, and Deck Caulked. Main Mast new.

She appears to be in good condition, eligible to remain Classed A 1

Committee's Minute 2nd May 185 4

Character assigned 12 A 1

J. S. Martin
 Certificate (if required)

No. _____ Survey held at _____ Date _____ 185 _____
 on the _____ Master _____
 Tonnage _____ Built at _____ When built _____
 By whom built _____ Owners _____
 Port belonging to _____ Destined Voyage _____
 If Surveyed Afloat or in Dry Dock _____

Last Survey, No. _____ Port of _____ Classed _____

The present Condition of the

Decks	Treenails	Windlass and Capstan
Waterways	Breasthooks and Stemson	Pumps
Comings	Transoms, Pointers, and Crutches	Boats
Upper Deck Beams & Fastenings	Timbers of the Frame	Masts, Yards, &c.
Lower Deck Beams & Fastenings	Keelsons	Sails
Planksheers	Clamps and Shelves	Anchors No. of
Sheerstrakes	Ceiling	Cables
Topsides	Rudder	Hawsers and Warps
Wales	Copper	Standing & Running Rigging
Plank (Bottom) and Counter	When put on	

General Observations and Opinion,

Committee's Minute _____ 185 _____

Character assigned _____



© 2019

Certificate (if required)

10N 634-0383