

ANNUAL SURVEYS.

19121

No. 335 Survey held at London Date May 22nd 1854
 on the Barke "Locknagar" Master Salgaroo
 Tonnage 380 Built at Sunderland When built
 By whom built Owners Park & Co
 Port belonging to Fraserburg Destined Voyage
 If Surveyed Afloat or in Dry Dock Nelson Dry Dock

Last Survey, No. 17040 Port of London Fraserburg Classed A. 1.
57

The present Condition of the

Decks <u>Good</u>	Treenails	Windlass and Capstan <u>which</u>
Waterways <u>Caulked</u>	Breasthooks and Stemson	Pumps
Comings <u>Good</u>	Transoms, Pointers, and Crutches	Boats
Upper Deck Beams & Fastenings <u>all good</u>	Timbers of the Frame <u>All good</u>	Masts, Yards, &c. <u>In good order</u>
Lower Deck Beams & Fastenings <u>where seen</u>	Keelsons <u>where</u>	Sails <u>and</u>
Planksheers	Clamps and Shelves <u>seen</u>	Anchors No. of <u>sufficient</u>
Sheerstrakes	Ceiling	Cables
Topsides <u>Caulked & good</u>	Rudder	Hawsers and Warps
Wales	Copper & Metal When put on <u>1833</u>	Standing & Running Rigging
Plank (Bottom) and Counter		

General Observations and Opinion, Now done, Caulked from Yellow Metal sheathing to waterway
stem She now appears in good and efficient condition and in my
 opinion eligible to remain classed A. 1. B. Maymonth

Committee's Minute 14th July 1854

Character assigned A. 1.

Certificate (if required)

No. 111 Survey held at London Date June 13th 1854
 on the Barke "Orator" Master J. Homan
 Tonnage 321 Built at Sunderland When built 1835
 By whom built Owners J. Allan &
 Port belonging to London Destined Voyage Madras
 If Surveyed Afloat or in Dry Dock Nelson Dry Dock

Last Survey, No. 18255 Port of London Classed SS 57 11^{*} A. 1.
C 4 53

The present Condition of the

Decks <u>Good</u>	Treenails	Windlass and Capstan
Waterways <u>4</u>	Breasthooks and Stemson	Pumps
Comings <u>6</u>	Transoms, Pointers, and Crutches	Boats
Upper Deck Beams & Fastenings <u>all good</u>	Timbers of the Frame <u>All good</u>	Masts, Yards, &c. <u>In good order</u>
Lower Deck Beams & Fastenings <u>where seen</u>	Keelsons <u>where seen</u>	Sails <u>4</u>
Planksheers	Clamps and Shelves <u>where seen</u>	Anchors No. of <u>sufficient</u>
Sheerstrakes	Ceiling	Cables
Topsides <u>Caulked & Good</u>	Rudder	Hawsers and Warps
Wales	<u>Yellow Metal</u> When put on <u>Now new</u>	Standing & Running Rigging
Plank (Bottom) and Counter	<u>Copper on Felt</u>	

General Observations and Opinion, Now done, hung in shores and caulked from
to keel to gunwale; bottom stripped of the Yellow Metal sheathing
and resheathed on Felt - She now appears fit for the conveyance of
dry and perishable cargoes and

Committee's Minute 14th July 1854

Character assigned A. 1.

Certificate (if required)