

ANNUAL SURVEYS.

19182

No. 395 Survey held at London Date June 30th 18 54
 on the Ship "Woolloomooloo" Master C Stewart
 Tonnage 645 Built at Aberdeen When built 1852
 By whom built 627 Owners Thompson
 Port belonging to Aberdeen Destined Voyage _____
 If Surveyed Afloat or in Dry Dock Lawender Dry Dock

Last Survey, No. 1536 Port of Aberdeen Classed 10 A. 1.
 52

The present Condition of the

| | | |
|---|---|--|
| Decks <u>Good</u> | Treenails _____ | Windlass and Capstan _____ |
| Waterways _____ | Breasthooks and Stemson _____ | Pumps _____ |
| Comings _____ | Transoms, Pointers, and Crutches _____ | Boats _____ |
| Upper Deck Beams & Fastenings <u>Good &</u> | Timbers of the Frame <u>All good</u> | Masts, Yards, &c. <u>In good order</u> |
| Lower Deck Beams & Fastenings <u>suff.</u> | Keelsons _____ | Sails <u>and</u> |
| Planksheers _____ | Clamps and Shelves <u>where seen</u> | Anchors No. of <u>sufficient</u> |
| Sheerstrakes _____ | Ceiling _____ | Cables _____ |
| Topsides <u>Good</u> | Rudder <u>Yellow Metal</u> | Hawsers and Warps _____ |
| Wales _____ | Copper <u>on Treenails</u> When put on <u>how new</u> | Standing & Running Rigging _____ |
| Plank (Bottom) and Counter <u>Caulked</u> | | |

General Observations and Opinion, Now done, Yellow Metal stripped, bottom Caulked and
resheathed with Yellow Metal on Treenails upper course, and paper from
thence to the keel. She now appears in good condition fit to remain
as classed A. 1. B. May in order

Committee's Minute 18th August 1854

Character assigned 10 A. 1. record & up

Certificate (if required)

No. 30 Survey held at London Date July 10th 18 54
 on the Ship "Aberfoyle" Master J. A. Hourse
 Tonnage 884 Built at Dumbarton When built 1852
 By whom built 965 Owners P. & J. Aitman
 Port belonging to Glasgow Destined Voyage Port Philip
 If Surveyed Afloat or in Dry Dock Hepp's Young's Dry Dock

Last Survey, No. 12192 Port of Liverpool Classed 9 A. 1.
 53

The present Condition of the

| | | |
|--|--|--|
| Decks _____ | Treenails _____ | Windlass and Capstan _____ |
| Waterways _____ | Breasthooks and Stemson _____ | Pumps _____ |
| Comings _____ | Transoms, Pointers, and Crutches _____ | Boats _____ |
| Upper Deck Beams & Fastenings <u>Good</u> | Timbers of the Frame <u>All good</u> | Masts, Yards, &c. <u>In good order</u> |
| Lower Deck Beams & Fastenings <u>where</u> | Keelsons <u>where seen</u> | Sails <u>and</u> |
| Planksheers <u>seen</u> | Clamps and Shelves _____ | Anchors No. of <u>sufficient</u> |
| Sheerstrakes _____ | Ceiling _____ | Cables _____ |
| Topsides _____ | Rudder <u>Yellow Metal</u> | Hawsers and Warps _____ |
| Wales _____ | Copper _____ When put on <u>1852</u> | Standing & Running Rigging _____ |
| Plank (Bottom) and Counter _____ | | |

General Observations and Opinion, She appears in good and efficient condition
and eligible to remain classed A. 1. B. W. Aitman

Committee's Minute 18th August 1854

Character assigned 9 A. 1.



© 2019

Lloyd's Register
 Foundation

Certificate (if required)

LN 635-0084